UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

5	S. LEASE SF-078897-A
6	. IF INDIAN, ALLOTTEE OR TRIBE NAME
7	. UNIT AGREEMENT NAME
8	B. FARM OR LEASE NAME Western Federal
2	8-Y
10	D. FIELD OR WILDCAT NAME So. Galleogs Fruitland
11	SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 18, T26N, R11W
12	COUNTY OR PARISH 13. STATE San Juan New Mexico
14	API NO.

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. oil well \mathbf{x} other well 2. NAME OF OPERATOR J. Gregory Merrion & Robert L. Bayless 3. ADDRESS OF OPERATOR P.O. Box 1541, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 790 FNL & 1850 FEL AT TOP PROD. INTERVAL: same AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

15. ELEVATIONS (SHOW DF, KDB, AND WD) 6096 ft. G.L.

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9–330.)

APR 1 4 1980

U. S. GEOLOGICAL SURVEY FARMINGTON, N. M.

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - 3-21-80 Rig up swabbing unit. Run sinker bar in and check for fill. Filled to 1270'. Rig down and moved.
 - 3-31-80 Run siphon string to 1268'. SDON.
 - 4-01-80 Circulate hole clean with pump truck. Lay down siphon string and swab. 12 runs to swab hole dry. Gas TSTM. Rig down.

APR 16 1970 APR 1 1980

APR 2011. COM.

BY SET 1985 Ft.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operator

DATE April 11, 1980

(This space for Federal or State office use)

 _ TITLE _

__ DATE .