UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on re-


	Form a	pprove	i. /		
	Budget	Bureau	1 /N o.	42-R	1424.
. LEASE	DESIGN.	ATION A	ND SE	CRIAL	NO.

DE	GEOLOGICAL SURVEY	SF 078937
SUNDRY (Do not use this form for Use "	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL GAS WELL WELL NAME OF OPERATOR	OTHER	7. UNIT AGREEMENT NAME N/A S. FARM OR LEASE NAME
Getty Oil Company	P.L. Davis 9. WELL NO.	
	ngton, New Mexico 87401 location clearly and in accordance with any State requirements.	#1E 10. FIELD AND FOOL, OR WILDCAT Basin Dakota
1190'FNL	. & 1170'FWL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26 T26N R11W
4. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OF PARISH 13. STATE
	6325' GR	San Juan New Mexico
6. CF	heck Appropriate Box To Indicate Nature of Notice, Report	t, or Other Data
NOTICE	OF INTENTION TO:	SUBSEQUENT REPORT OF:

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:				
		PULL OR ALTER CASING			WATER SHUT-OFF	REPAIRING WELL	٦
TEST WATER SHUT-OFF		PULL OR ALTER CASING			WATER SHUT-OFF	REI AIRING WEED	-
FRACTURE TREAT		MULTIPLE COMPLETE			FRACTURE TREATMENT	ALTERING CASING	-1
SHOOT OR ACIDIZE		ABANDON*			SHOOTING OR ACIDIZING	ABANDONMENT*	_
REPAIR WELL		CHANGE PLANS	XX		(Other)		
(Other)			<u> </u>		(NOTE: Report results of r Completion or Recompletion	nultiple completion on Well n Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

The estimated top of the Ojo Alamo Formation is 540'.



nmoce

*See Instructions on Reverse Side

APPROVED BY

18. I hereby certify that the foregoing is true and correct

George Lapaseotes (This space for Federal or State office use)

CONDITIONS OF APPROVAL, IF ANY: