

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYForm Approved.  
Budget Bureau No. 42-R1424

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR  
Southern Union Exploration Company
3. ADDRESS OF OPERATOR  
1217 Main Street, Dallas, TX 75202
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 810' FSL & 1520' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

- TEST WATER SHUT-OFF ☐ ☒  
FRACTURE TREAT ☐ ☐  
SHOOT OR ACIDIZE ☐ ☐  
REPAIR WELL ☐ ☐  
PULL OR ALTER CASING ☐ ☐  
MULTIPLE COMPLETE ☐ ☐  
CHANGE ZONES ☐ ☐  
ABANDON\* ☒ ☐  
(other) ☐ ☐

5. LEASE  
NM 33030

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
SX Federal 259. WELL NO.  
110. FIELD OR WILDCAT NAME  
Pictured Cliffs11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 25, T26N, R13W12. COUNTY OR PARISH  
San Juan13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6138' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Request permission to plug & abandon this well, no commercial zones of production were found.

Purpose to cement from TD (1240') to 1000' and from 236' to surface. The 7" surface casing will be cut off and the location will be cleaned up.

Install 4' Plug + Abandonment Marker

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct. Drilling &  
SIGNED [Signature] TITLE Production Eng. DATE 2/25/81

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

NMOCC

FEDERAL SURFACE

Attachment to Notice of  
Intention to Abandon

U. S. GEOLOGICAL SURVEY  
P. O. Box 959  
Farmington, New Mexico 87401

4-30-81

Re: Permanent Abandonment

Well: #1 SX Federal 25

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Lands".
2. The Farmington office (telephone (505) 335-4510) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. The surface management agency is to be notified when surface rehabilitation is complete.
6. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 8:00 A.M. to 5:00 P.M.  
Farmington Personnel to be notified:

Home Telephones:

Ray Swanson: Petroleum Engineering Technician - 325-8189  
Fred Edwards: Petroleum Engineering Technician - 325-7885  
Ken Baker: Petroleum Engineering Technician - 327-2170