

(3/25/81): 3 Copies

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR

MESA PETROLEUM CO.

3. ADDRESS OF OPERATOR

80264

1660 LINCOLN, 2800 LINCOLN CENTER, DENVER, CO

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 315' FNL & 720' FVL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

(other) Commence drilling operations, set casing, and test BOP

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The above well was spudded at 9:00 PM March 19, 1981. A 12-1/4" hole was drilled to 479'. Ran, set, and cemented 11 new joints of 8-5/8" 24#/ft. K-55 ST&C casing @ 464' with 265 sxs Class "B" cement containing 3% CaCl<sub>2</sub>. Circulated 20 bbls slurry to surface. Nipped up BOP and tested to 1000<sup>2</sup> psi for 30 minutes - held OK.

Subsurface Safety Valve: Manu. and Type

Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

*[Signature]*

TITLE Div. Drlg. Super. DATE March 24, 1981

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NMOCC

ACCEPTED FOR RECORD

MAR 31 1981

\*See Instructions on Reverse Side

FARMINGTON DISTRICT

BY



(NOTE: Report results of multiple completions zone change on Form 9-330.)