Form 3160-5 (November 1994)

(Instructions on reverse)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-01/35
Expires November 30, 2000

6. If Indian, Allottee or Tribe Name

5. Lease Serial No.

ISF	-	ี ก	7Q:	₹1	(

SUNDRY NOTICES AND REPORTS ON WELLS

abandoned well. Use Form 3160-3 (APD) for such propostate - 3 [: 2]

Do not use this form for proposals to drill or to re-enter an

SUBMIT IN TRIPLICATE Other instruction but the ree side 7. If Unit or CA/Agreement, Name and/or No 1. Type of Well 8. Well Name and No. Oil Well X Gas Well Other #5E Schwerdtfeger A 2. Name of Operator Cross Timbers Operating Company 9. API Well No DIST. 3 3b. PhoneNo. (include area code) 3a. Address 300-45-24790 NM 87401 Farmington, 2700 Farmington Ave., Bldg. K. Ste 1 10. Field and Pool, or Exploratory Area Undesignated Gallup 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Basin Dakota 11. County or Parish, State 850' FNL & 1,060' FEL, Unit A, Sec 6, T27N, R08W San Juan NM CHECK APPROPRIATE BOX(ES) TO INDICATE NATUREOF NOTICE, REPORT, OR OTHERDATA TYPE OF ACTION TYPE OF SUBMISSION X Production (Start/Resume) Water Shut-Off Deepen Notice of Intent Acidize Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Water Disposal Convert to Injection Plug Back Describe Proposed or CoommpletedOperation (clearly state all pertinent details, including estimated starting date of any proposed work and approximateduration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final AbandonmentNotices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) Cross Timbers Operating Co. has completed the DHC operation on the above mentioned well. 8/19/99 MIRU PU. TOH w/Gallup production tbg. 8/20/99 PU bit & tbg and CO sand fill to top of fish @ 6,998' KB (CIBP @ 7.000' KB). 8/21/99 PU & TIH w/spear & tbg. Attempted to recover a sleeve (fish) fr/the CIBP setting tool @ 6,998'. Unable to rec fish. TOH w/tbg & spear. 8/24/99 PU & TIH w/mill & tbg. Milled up fish (@ 6,998')& CIBP (@ 7,000'). TOH w/tbg & mill. 8/25/99 TIH w/bit & tbg. Cleaned out fill below the Dakota to PBTD using air/foam. TOH w/tbg & bit. 8/26/99 TIH w/production tbg as follows: 222 jts 2-3/8', 4.7#, J-55, EUE, 8rd tbg, API SN & notched Landed EOT @ 7,030' KB. SN @ 7,028' KB. RWTP producing the Gallup & Dakota formation together via a single string of tbg per NMOCD order DHC-2405. I hereby certify that the foregoing is true and correct Name(Printed/Typed) Production Engineer Jeffery W. Patton 9/01/99 ACCEPTED FOR RECORD THIS SPACE FOR FEDERAL OR STATE OFFICE USE DateOC 2 1999 Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. LD OFFICE EARMINGTON/FI Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any departmentor agency of the United States any false, fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD