

All distances must be from the outer boundaries of the Section.

Operator Union Texas Petroleum Corporation		Lease Newsom B		Well No. 7-E	
Unit Letter K	Section 8	Township 26N	Range 8W	County San Juan	
Actual Footage Location of Well: 1750 feet from the South line and 1810 feet from the West line					
Ground Level Elev. 6350	Producing Formation Gallup-Dakota		Pool Undesignated-Basin		Dedicated Acreage: 160 - W320

1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below.
2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).
3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☐ Yes ☒ No If answer is "yes," type of consolidation _____

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) _____

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Division.

RECEIVED

FEB 16 1984

OIL CON. DIV.
DIST. 3

RECEIVED

FEB 15 1984

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

ACCEPTED FOR RECORD

FEB 13 1984

FARMINGTON RESOURCE AREA

BY _____

NMOC

CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

J. A. Edmister

Name

J. A. Edmister

Position

Engineering Analyst

Company

Union Texas Petroleum Corp.

Date

February 14, 1984

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed

Registered Professional Engineer
and/or Land Surveyor

Michael Daly

Certificate No.
5992