

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
El Paso Natural Gas Company

3. Address & Phone No. of Operator
Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec, T, R, M.
830'N, 1160'E Sec. 19, T-26-N, R-10-W, NMPM

5. Lease Number

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name
Huerfano Unit

8. Well Name & Number
Huerfano Unit #244E

9. API Well No.

10. Field and Pool
Basin Dakota

11. County and State
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

- ☐ Notice of Intent
- ☒ Subsequent Report
- ☐ Final Abandonment

Type of Action

- ☐ Abandonment
- ☐ Recompletion
- ☐ Plugging Back
- ☒ Casing Repair
- ☐ Altering Casing
- ☐ Other
- ☐ Change of Plans
- ☐ New Construction
- ☐ Non-Routine Fracturing
- ☐ Water Shut Off
- ☐ Conversion to Injection

13. Describe Proposed or Completed Operations

01-28-91 MOL&RU. Kill well w/30 bbls. KCl wtr. ND WH. NU BOP. Work stuck tbg. SDFN.

01-29-91 TOO H w/tbg. TIH w/scraper to 5975'. Circ hole clean w/2% KCl wtr. TOO H w/scraper. SDFN.

01-30-91 TOO H w/tbg. TIH w/pkr & BP set @ 4380'. Test BP 1500#, ok. Pull to 4064'. Test csg from btm of pkr to BP 1500#, ok. Found bad csg 3071-4064'. TOO H w/pkr. TIH w/FBP, testing csg 1500#. Found upper hole in csg @ 3066'. Retest csg 3066-4064, csg leak throughout. Pull pkr to 2809' & set. Pump into csg leak. SDFN

01-31-91 Release FBP, run down to 4100'. Spot 2 sx sand on RTBP @ 4380'. Spot 70 sx Class "B" neat cmt 3000-4100'. Pull up hole to 2809'. Set pkr, reverse circ 3 bbl. around pkr. Pump 130 sx Class "B" neat cmt down tbg into csg. Displace to 2870'. Release pkr, pull up to 2551'. Reverse circ 20 bbl. around pkr. Reset pkr and pump 1 bbl. squeeze. WOC. SDFN.

cont'd on back

14. I hereby certify that the foregoing is true and correct.
Signed John Deafield Title Regulatory Affairs Date 2-7-91

FEB 26 1991

(This space for Federal or State office use)

APPROVED BY _____
CONDITION OF APPROVAL, IF ANY:

TITLE _____

FARMINGTON RESOURCE AREA
BY JS DATE _____

Huerfano Unit #244E, cont'd.

02-01-91 TOO H w/pkr. TIH w/scraper, tag TOC @ 2914'. Drl cmt
2914-3525'. Circ hole clean. SI. SDFN.

02-02-91 Drl out of cmt @ 4126'. Circ hole clean. Tag BP @ 4380'. PT csg
550#/15 min, ok. Circ sand off BP. Pull tbg to 2800'. SI. SD
for weekend.

02-04-91 TOO H w/scraper. TIH, blow down w/air & foam. Tag plug @ 4380'.
TOO H w/BP. TIH, blow down w/air & foam. Blowing well @ 6055'.
SDFN.

02-05-91 Pull tbg to 4500'. Unload w/air. TIH, tag fill 2 6400'. CO to
6535'. Blow w/air & foam mist. TOO H. SDFN.

02-06-91 Ran 69 jts 2 3/8", 4.7#, J-55 EUE tbg landed @ 6467'. SN @
6435'. Model "R" pkr @ 4255'. ND BOP. NU WH. Swabbed.
Released rig.