Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** SUNDRY NOTICES AND REPORTS ON WELLS

Budget Bureau No. 1004-0135 Expires: March 31, 1993 NMNM-36590

FORM APPROVED

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir, Use "APPLICATION FOR PERMIT" for such proposals		7. If Unit or CA. Agreement Designation
SUBMIT IN TRIPLICATE		–
1. Type of Well Oil Well X Ga	s Well Other	8. Well Name and No. Rick Wells Well No. 1
2. Name of Operator		9. API Well No.
Central Resources, Inc. for Giant Exploration & Production Company		30-045-27317
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area
P.O. Box 2810, Farmington, New Mexico 87499 (505)326-3325		Basin Fruitland Coal
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
2510' FNL. 790' FEL [®] Sec. 8, T26N, R13W		San Juan, New Mexico
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION		
	X Abandonment	Change of Plans
X Notice of Intent	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Final Abandonment Notice	Other	Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
directionally drilled, give subsurface locations and measured and due vertical depuis for an inalized and zones permitted and worth,		
		1
Central Resources, Inc. pla	ns to plug and abandon the subject well as fol	llows:
1) Plug will be set from the bottom perforation (1427') to the surface (124.6 cuft) by mixing and		
pumping 109 sks (128.6	cuft) of Class B neat cement.	
2) After cement has set up, tag top and refill hole, if necessary.		
 2) After cement has set up, tag top and refill hole, if necessary. 3) Cut off wellhead and install a regulation dry hole marker. 4) Rehabilitate location. 		
4) Rehabilitate location.		
4) Renadilitate location.		- デー in ()
		취임 목 목 기원 :
	₹ 1883 - 1 1 1 1	OTO FANALASION, NM
	• • • •	2 -
		≤-

14. I hereby certify that the foregoing is true and correct Date ... 2/7/97 Title Production Engineer Gregory E. McIntosh FFR (This space for spiral of Swe office use) Date Title Approved by Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false fictitious or fraudulent statements or representations as to any manner within its jurisdiction.