



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO

NM-33047 et al. (WC)
3162.3-1 (019)

Merrion Oil & Gas Corporation
P.O. Box 840
Farmington, NM 87499

OCT. 10 1991

RECEIVED

OCT 11 1991

OIL CON. DIV
DIST. 3

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 5 Hi Roll, sec. 35, T. 27 N., R. 13 W., San Juan Co., NM, lease
NM-33047.
- ✓ 2. 2 Nelson, sec. 9, T. 26 N., R. 12 W., San Juan Co., NM, lease
SF-078944-A.
3. 11 Southland, sec. 9, T. 26 N., R. 13 W., San Juan Co., NM, lease
NM-12235.
- ✓ 4. 8 Southland, sec. 10, T. 26 N., R. 13 W., San Juan Co., NM, lease
NM-12235.
5. 1 Star Federal 30, sec. 30, T. 26 N., R. 12 W., San Juan Co., NM, lease
NM-0560223.
- ✓ 6. 5 Morgan, sec. 31, T. 27 N., R. 12 W., San Juan Co., NM, lease
SF-080238-A.
- ✓ 7. 7 Delhi Taylor A, sec. 17, T. 26 N., R. 11 W., San Juan Co., NM, lease
SF-079679.
8. 2 Frontier, sec. 5, T. 26 N., R. 12 W., San Juan Co., NM, lease
SF-081102-A.
9. 9 Southland, sec. 11, T. 26 N., R. 13 W., San Juan Co., NM, lease
NM-12235.
10. 10 Southland, sec. 3, T. 26 N., R. 13 W., San Juan Co., NM, lease
NM-12235.
- ✓ 11. 2 Serendipity, sec. 26, T. 26 N., R. 13 W., San Juan Co., NM, lease
NM-33031.

As discussed with Steven Dunn of your company on, October 8, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

ABANDONED LOCATIONS

F

30-045-28200

09-04-90

F. Loc. 790/N; 1190/E Elev. 6144 GL Spd. _____ Comp. _____ TD. _____ PB. _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. _____ @ _____ W. _____ Sx. Int. _____ @ _____ W. _____ Sx. Pr. _____ @ _____ W. _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____ T Gas
 R
 A
 N
 S

BO/D		Grav. _____		1st Del. Gas _____								
MCF/D After _____		Hrs. SICP _____		PSI After _____		Days GOR _____		1st Del. Oil _____				
TOPS		NITD <u>X</u>		Well Log		TEST DATA						
Ojo Alamo		C-103		Plat <u>X</u>		Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104		Electric Log								
Fruitland				C-122								
Pictured Cliffs		Ditr		Dfa								
Chacra		Datr		Dac								
Cliff House												
Menefee												
Point Lookout												
Mancos												
Gallup												
Greenhorn												
Dakota												
Entrada												
				Acres <u>N/320</u>								

P
o
o
i

BasinFrCoal Co. SJ S 26 T 26N R 13W UA Oper. Merrion Oil & Gas Lse. Serendipity No. 2

Serendipity #2

A-26-26N-13W

MERRION OIL & GAS CORP.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410