Form 9-881 a (Feb. 1981)

(SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Lease No. SF-079050-B Unit San Juan 28-6

## SUNDRY NOTICES AND REPORTS ON WELLS

SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
K NATURE OF REPORT, NOTICE, OR OTHER DATA)		

Well No. 113 is located 790 ft. from S line and 1850 ft. from W line of sec. 26

SE/4 SW/4 Sec. 26 28 N 6 N NEW (Meridian)

Basin Dakota Rio Arriba New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the statistical above sea level is 6617 ft. G.L.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

	Drilled out cement, tested cag. squeezed 75 sx reg. 1% Halad 9 3500#.	+ 2% calcium c	hloride. Max.	adnesas bassen
10/19/63	Drilled cement from 4900-5024'. Drilled retainer @ 5030', cemen	Pressure tes	t w/1700# fer : '76'. Tested w	30 mln., held 0# /1500# held 0K.
10/20/63	Drilled BP @ 7624', CO to 7860' Set production packer @ 7623'. SI prep to test.	1		
•	•			RELEVED
	tand that this plan of work must receive approval in wr		\ <b>O</b>	by be commondig 63
Company	Bets Development Co.			IL CON. COM.
Address	234 Petr. Club Plaza		Original signed	By
	Farmington, New Mexico	Ву	JOHN T. HAMI	PIC.
***********		Title	Manager	