UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT RECEIVED

BLM		
Sundry Notices and Reports on Wells 95 NG 28 AM 7:56	*	
1. Type of Well GAS 93 805 20 Rth 18 31 070 FARMINGION, NU	5.	Lease Number SF-080430 If Indian, All. or Tribe Name
<u> </u>	7.	Unit Agreement Name
2. Name of Operator MERIDIAN ©IL	8.	San Juan 28-6 Unit Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	San Juan 28-6 U #2 API Well No.
4. Location of Well, Footage, Sec., T, R, M 890'FNL, 990'FEL, Sec.18, T-28-N, R-6-W, NMPM		30-039-07437 Field and Pool Blanco Mesaverde County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT	, OTHER	DATA
X Subsequent Report Plugging Back Non-Ro Casing Repair Water	Shut of	tion Fracturing
13. Describe Proposed or Completed Operations		
7-31-95 MIRU. ND WH. NU BOP. TOOH w/184 jts 2 3/8" tbg. 5588'. Load tbg. PT to 1000 psi, OK. TIH to re 8-1-95 TOOH. TIH w/pkr, set @ 5200'. Load csg w/195 bbf failed. Csg will not hold wtr. ND BOP. NU WH.	etrieve L wtr. <i>P</i>	standing valve. SDON Attempt to PT csg.
Well is scheduled for casing repair in 1996. A detailed p	procedur	ee will be submitted.
14. I hereby certify that the foregoing is true and correct. Signed May Malhueld Title Regulatory Administrate	or Date	e 8/23/95
(This space for Federal or State Office use) APPROVED BY	ate ACC	EPTED FOR RECORD
		AUG 3 0 1995
	FARM	INGTON DISTRICT OFFICE

NMOCD