

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1555' FNL, 790' FEL, Sec. 24, T-28-N, R-5-W, NMPM

5. Lease Number
SF-079520

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
San Juan 28-5 Unit
San Juan 28-5 U #98

9. API Well No.
30-039-21820

10. Field and Pool
Basin Dakota

11. County and State
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent

☐ Abandonment

☐ Change of Plans

☐ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☒ Other - Pay add

13. Describe Proposed or Completed Operations

It is intended to add pay to the Dakota formation of the subject well in the following manner:

MIRU. ND WH. NU BOP. Test BOP. TOOH with tubing. Pressure test casing to 1000 psi. Drill out below existing casing to just above base of Dakota. Selectively perforate casing above casing shoe. TIH with packer and frac string. Fracture stimulate Dakota (including open hole section) with sand and gelled water. Clean out to total depth after frac. Rerun tubing and return well to production.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (SHL8) Title Regulatory Administrator Date 1/10/96

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

Date

CONDITION OF APPROVAL, if any:

APPROVED

JAN 17 1996

DISTRICT MANAGER