

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED
BLM MAIL ROOM

~~Sundry Notices and Reports on Wells~~ 95 SEP -5 PM 2:42

1. Type of Well
GAS

RECEIVED
SEP - 8 1995

070 FARMINGTON, NM

5. Lease Number
SF-079727

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

2. Name of Operator

MERIDIAN OIL OIL CON. DIV.

DIST. 3

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
Valdez #1

9. API Well No.
30-039-22078

10. Field and Pool
Choza Mesa Pict.Cliffs

11. County and State
Rio Arriba Co, NM

4. Location of Well, Footage, Sec., T, R, M

860' FSL, 1590' FEL, Sec.9, T-28-N, R-4-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
☐ Notice of Intent	☒ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☐ Other -
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut off
	☐ Conversion to Injection

13. Describe Proposed or Completed Operations

8-24-95 MIRU. TIH w/2 1/4" gauge ring to 3966'. POOH. TIH w/1 13/16" gauge ring to 4418'. TOOH. ND WH. NU BOP. Pump 15 bbl wtr down tbq. Plug #1: pump 16 sx Class "B" cmt @ 3819-4400'. TOOH to 2500'. SDON.

8-25-95 TIH to 4418', did not tag cmt. Establish circ w/13 bbl wtr. TOOH. TIH w/2 7/8" cmt retainer, set @ 3938'. PT csg to 500 psi/5 min, OK. Can not pump ball out of retainer. (Verbal approval to change plans from Wayne Townsend, BLM). Plug #2: pump 4 sx Class "B" cmt on top of cmt retainer @ 3793-3938'. TOOH to 3807'. Reverse circ hole clean w/14 bbl wtr. POOH. TIH, perf 4 sqz holes @ 3800'. Establish injection. Plug #3: pump 50 sx Class "B" cmt outside csg, leave 22 sx Class "B" cmt inside csg. Displace to 3000'. Sqz to 900 psi. WOC. SD for weekend.

8-28-95 TIH, tag cmt @ 3159'. TOOH to 2463'. Perf 4 sqz holes @ 2463'. Establish injection. Plug #4: pump 50 sx Class "B" cmt outside csg, 29 sx Class "B" inside 2 7/8" csg. Displace cmt to 1600'. Sqz to 600 psi. WOC. Tag TOC @ 1516' POOH. TIH. Perf 2 sqz holes @ 284'. Establish circ out bradenhead w/11 bbl wtr Plug #5: pump 119 sx Class "B" cmt @ 284' to surface. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Install dry hole marker w/8 sx Class "B" cmt RD. Rig released. Well plugged and abandoned 8-28-95.

14. I hereby certify that the foregoing is true and correct.

Signed *Deana D. Bland* Title Regulatory Administrator Date 8/31/95

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

APPROVED

SEP 06 1995

DISTRICT MANAGER

NM000