

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN THE MANNER SPECIFIED - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMSF078081
2. Name of Operator BURLINGTON RESOURCES O&G CO LP		6. If Indian, Allottee or Tribe Name EASTERN NAVAJO
3a. Address P O BOX 4289 FARMINGTON NM 88401	3b. Phone No. (include area code) Ph: 505.326.9727 Fax: 505.326.9781	7. If Unit or CA/Agreement, Name and/or No. NMMN78394A
4. Location of Well (BIA, or Survey Description) Sec 33 T27N R9W N1/4 SW 1/4 SL 0.00FWL 36.52905 N Lat, 107.1757- W Lon		8. Well Name and No. HUERFANITO 31
		9. API Well No. 30-045-06132-00-S1
		10. Field and Pool, or Exploratory BLANCO
		11. County or Parish, and State SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMITTANCE	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Incident	<input type="checkbox"/> Acidize
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Fracture Treat
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Recomplete
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Other

13. Describe proposed or completed work (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to be completed horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond Form if required. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once the operation is completed. Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the well is ready for production.)

It is intended work on this well in the following manner:

Pull 1" tubing out of well to 2284' in the Pictured Cliffs formation. Run out from 2284' to new total depth @ 2404' in the Pictured Cliffs formation. Cement 1" tubing with Class "G" cement. Selectively perforate and fracture stimulate the Pictured Cliffs formation. Return the well to production as a Pictured Cliffs completion.

- Please comply with Onshore Order No. 2 while performing drilling operations.

14. I hereby certify that the above information is true and correct.	Submission #13027 verified by the BLM Well Information System
Name: Adrienne Garcia	BURLINGTON RESOURCES O&G CO LP, sent to the Farmington
	WISS for processing by Adrienne Garcia on 07/24/2002 (02AXG0408SE)
Signature: [Signature]	Title: REGULATORY ADMINISTRATOR
	Date: 07/24/2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved: Jim Lovato	Title:	Date: JUL 26 2002
Conditions: This notice does not warrant or certify that the above information is true and correct, which would be the responsibility of the operator.	Office:	

Title 18 U.S.C. 11212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false or misleading representations as to any matter within its jurisdiction.

** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ** REVISED ** REVISED **

NMOCD