

NO. OF COPIES RECEIVED	5
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	3

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fed. <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator William C. Russell		8. Farm or Lease Name Hammond (NM03603-A)
3. Address of Operator 1775 Broadway, New York, New York		9. Well No. 3
4. Location of Well UNIT LETTER F 1650 FEET FROM THE N LINE AND 1650 FEET FROM THE W LINE, SECTION 35 TOWNSHIP 27N RANGE 8W NMPM.		10. Field and Pool, or Wildcat S. Blanco P.C.
15. Elevation (Show whether DF, RT, GR, etc.) GR 6114		12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Great Lakes Oil & Chemical Company #3 Hammond
Plugged and Abandoned 12/12/68 T.D. 2283**

**Circulated cement down 1" tubing and loaded 5 1/2" casing to surface.
Pumped ten sacks cement down 5 1/2" casing. Pumped five sacks cement
down bradenhead. Pulled NO casing or tubing. Removed wellhead and
erected P & A marker. Cleaned location.**



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>William C. Russell</u>	TITLE Operator	DATE 12/12/68
APPROVED BY <u>Emery C. Clumet</u>	TITLE <u>Sup Dist III</u>	DATE
CONDITIONS OF APPROVAL, IF ANY:		