Form 3350-5 November 1983) Formerly 9-331)	UNITED STATES PARTMENT OF THE INTE		Budget Eureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. SF-079232
SUNDRY (Do not use this form Use	NOTICES AND REPORTS for proposals to drill or to deepen or pl "APPLICATION FOR PERMIT—" for au	ON WELLS ug bark to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAB			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	OTHER	0CT 3 0 1985	8. FARM OR LEASE NAME
Tenneco Oil Compan	У	OIL CON. DIV.	Bolack C. IS 9. Wall No.
P 0 Box 3249 F 4. Location of Well (Report See also space 17 below.)	nglewood, CO 80155	ANY STATE REQUIREMENTS V E D	10. FIRLE AND POOL, OR WILDCAT
At surface	•		S 31anco PC 11. SBC., T., R., M., OR BLK. AND BUXYST OR AREA
990' FNL, 990' FEL		OCT 2.5 1985	Sec. 28, T27N R8W
14. PERMIT NO.	15. BLEVATIONS (Show whether	BUREAU OF LAND MANAGEMENT	12. COUNTY OF PARISH 13. STATE San Juan NM
16.	heck Appropriate Box To Indicat	FARMINGTON RESOURCE AREA	
	OF INTENTION TO:		DENT REPORT OF:
TEST WATER SEUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
BROOT OR ACIDIZE	CHANGE PLANS	Other) Production	liner ABANDONMENT*
(Other)	CHANGE PLANS	(Norg: Report results Completion or Recoup	of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPUSED OR COMP proposed work. If well nent to this work.) *	LETED OPERATIONS (Clearly state all pert is directionally drilled, give subsurface	inent details, and give pertinent dates, locations and measured and true vertice	including estimated date of starting any al depths for all markers and zones perti-
10/11/85 MIRUSU.			
2-3/8" bit sub w/6 Tally, pick up and Cmt w/140 sxs (217 Bumped the plug fo	I w/2% KCl wtr. Change 5-1/4" bit. Tagged the 1 RIH w/3-1/2" J-55 EUE v cu ft) thixotropic 10:00 allowed by 1 barrel of a cmt at 1200'. 70 jts, 2	fill at 2120'. Cleaned w/slotted bull plug & Or O cmt + 1/4 lb of floce cetic acid. Run a tempe	out to PBID w/foam. nega baffle on btm. le + 6-1/4# gilsonite
10/14/85 Cut off Logged from PBTD	3-1/2" csg. Install 3- to 1700'.	1/2" x 1-1/4" wellhead.	RIH w/GR/Neutron/CCL.
2 JSPF @ 2134'-58' w/2000 gal. 15% we psi. Injection ra	'. (24', 48 holes). Br Piahted HCL & 72 1.1 S.	oke down the formation, G. Ball sealers. Forma IP = 50. Acid away at	/-1/2 EPM, 840 psi. Baii
hole w/tbg and mi	ll. Roundtrip impressio	n block. Had frac ball	e ring. Come out of the s looking up. RIH w/junk
SIGNED State of	1) - Linicy TITLE	SP. Regulatory Analyst	DATE 10/22/95
(This space for Federal or			ACCEPTED FOR PECORD
APPROVED BY	TITLE _		DATE
	*See Instruct	tions on Reverse Side	FARMING TON MUCCONDE AREA

Form approved.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Form 3160-5	UNITED STATES	SUBMIT IN TRIPLICATE	Form approved. Budget Bureau No. 1004-0135
Voriember 1002)	RTMENT OF THE INTI	(Other Instruction	Expires August 31, 1985 5. LEAST DESIGNATION AND SEELAL NO.
	REAU OF LAND MANAGEM		SF-079232
SUNDRY N	OTICES AND REPORT	S ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS XX OTHE			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		•	S. PARM OR LEASE WAME
Tenneco Oil Company			Bolack C LS 9. WELL NO.
D 0 Roy 32/19 Engle	ewood, CO 80155		1
4. LOCATION OF WELL (Report locati See also space 17 below.) At surface	ion clearly and in accordance with	RECEIVED	S. Blanco PC 11. SDC, T., B., M., OR BLK. AND
990' FNL, 990' FEL		00T 2 5 193 5	Sec. 28, T27N R8W
14. PERMIT NO.	15. BLEVATIONS (Show whether	FARMINGTON RESOURCE AREA	12. COUNTY OR PARISH 18. STATE San Juan NM
16. Check	Appropriate Box To Indical	e Nature of Notice, Report, or (Other Data
	NTENTION TO:	• • •	QUENT REPORT OF:
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Production (Note: Report result Completion or Recom	REPAIRING WELL ALTERING CASING ABANDONMENT® Incr s of multiple completion on Well pletion Report and Log form.)
nent to this work.) *		libent details, and give pertinent dates locations and measured and true vertice bugh frac balls. POOH v	s, including estimated date of starting any cal depths for all markers and sones perti-
10/15/85 RIH w/tbg at perf debris. Worked w/50,000 gal of 70Q fo psi. Shut the well in	nd mill. Mill 30 mir the tbg to btm. Blow oam w/20# gel and 85, n for 2 hrs. Flow ba ll w/2% KCl. RIH w/1	n made 6-7" of hole. Revithe well clean. POOH, 000# of 20/40 sd. AIP ack to pit thru 1/2" tag1/4" tbg, SN 1 jt off	eversed out frac balls and Frac dwn csg at 30 BPM = 1950 psi. ISIP = 1400 oped bull plug. btm. Tag the sand fill
at 2145'. CO the PBTE w/nitrogen. NDBOP. !			KB. Kicked well around
			EGINED
			EBEIVED OCT 30 1985 OIL ON. DIV. DIST. 3
18. I hereby certify that the foregoi	<u>_</u> '	Senior Regulatory Analy	is less trees
(This space for Federal or State	e office use)		
APPROVED BY	IF ANY:		DATE

*See Instructions on Reverse Side