


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION

DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SANTA FE
Land Office
Lease No.
Unit



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Schwerdtfeger #10
C 34 E 16 N

July 13, 1951

Well No. 10 is located 990 ft. from ~~13~~ line and 1650 ft. from ~~16~~ line of sec. 16
W 1/4 16 27N 11W N.M.P.M.

1. Kutz Canyon
(Field)

(Twp.) San Juan
(County or Subdivision)

(Range) 16
(Meridian) New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is ft.

NOT DETERMINED

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

1. Drill surface hole and run and set approximately 100' 2-5/8" surface casing and cement to surface.
2. Test surface casing, cement plug and drill to base of Pictured Cliffs sandstone at approximately 2000'.
3. Run electric log to total depth.
4. Run and set approximately 1900' of 5 1/2" 8-40 1/2 casing on top of Pictured Cliffs sandstone and cement with 150 sacks of cement.
5. Move off rotary tools, test production string cement plug, drill cement plug, clean out to bottom and shoot with nitro shot.
6. Clean out after shot and complete well ready for production.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

THE FRONTIER REFINING COMPANY
Company
410 BOSTON BUILDING
Address
DENVER, COLORADO

By *A.C. Parson*
A.C. Parson, Geologist
Title

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPlicate)

NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ACIDIZING
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO DRILL	

01

1020

is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____

(field) (County or Township) (State or Territory) (Sec. and 36c No.) (Town) (Range)

The elevation of the deck floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sand; weight, area, width, and length of proposed borrowings; indicate mudblowing jobs; cementing points; and all other important work)

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be conducted.

С. 10

44-38861-100

By

111