

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Louis Dreyfus Natural Gas Corporation

3. Address and Telephone No.

(405) 749-1300

14000 Quail Springs Pkwy, Suite 600, Oklahoma City, OK 73134

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 990' FEL

(NE NE) Sec 12-T27N-R12W

5. Lease Designation and Serial No.

SF-079116

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Hancock #8

9. API Well No.

30-045-06737

10. Field and Pool, or Exploratory Area

West Kutz, P. C.

11. County or Parish, State

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SEE ATTACHED PROCEDURE.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct

Signed

Menton Shaw

Title

Production Engineer

Date

September 14, 1993

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

NMOCD

APPROVED

Date

SEP 21 1993

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

September 14, 1993

HANCOCK #8 (PC)
NE, NE, SEC 12, T27N, R12W
SAN JUAN COUNTY, NM

PLUG & ABANDONMENT PROCEDURE:

1. MOL and RUSU. Comply to all NMOCD, BLM and company safety rules and regulations.
 2. Blow well down; kill with water if necessary. ND wellhead and NU BOP and stripping head, test BOP.
 3. POH and LD 1" tubing (1500' \pm).
 4. PU 2-3/8" tubing work string with open end and RIH; tag bottom; pump 10 bbls water down tubing.
 5. Plug #1 from TD to 1700' with 50 sxs Class B cement (fills open hole, covers PC and Fruitland tops. POH and WOC.
 6. RIH and tag cement; circulate hole with water. Pressure test casing to 500#; mix and spot approximately 33 bbls 8.4# 40 vis mud from top of cement to 767'. POH with tubing.
 7. Perforate 4 holes at 767' (Ojo Alamo from 600' to 717', estimated from offset log). PU 7" cement retainer and RIH; set at 700'; pressure test tubing to 1000#; establish rate into holes.
 8. Plug #2 from 767' to 550' with 118 sxs Class B cement, squeeze 55 sxs outside casing and leave 63 sxs inside (100% excess outside casing and 50% inside). POH to 400'. Mix and spot 10 bbls 8.4# 40 vis mud from 400' to 141'; POH and LD tubing.
 9. Perforate 2 holes at 141'. Plug #3 from 141' to surface with approximated 70 sxs Class B cement, circulate good cement to surface. Shut in well and WOC. Cut off wellhead below surface casing flange, install P & A marker. Rig down and move off location.
 10. Restore location per BLM stipulations.
-

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
1235 La Plata Highway
Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 8 Hancock

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
2. **Mike Flaniken** with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
3. The following modifications to your plugging program are to be made (when applicable):

1.) Spot a cement plug from 1485' to 1385'
inside the casing plus 50 % excess.
(Top of Fruitland @ 1435')

2.) Extend Oso Alamo cement plug from 767'-550'
to 767'-470'. Adjust cement volumes.

Office Hours: 7:45 a.m. to 4:30 p.m.
