Form 9-331 (May 1063)	UNITED STATES DEPARTMENT OF THE INGEOLOGICAL SURVE	_	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAB TO OTHER			7. UNIT AGRESMENT NAME
2. NAME OF OPERATOR Tenneco Oil Company 8. ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado 81301			8. FARM OR LEASE NAME: Bolack "B"
			9. WHILE NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2250 FNL, 1020 FWL Unit E			10. FIELD AND POOL, OR WILDCAT Basin Dakota 11. BEC., T., R., M., OR BLE. AND BURNEY OR AREA
14. PERMIT NO.	PERNIT NO. 15. BLEVATIONS (Show whether DF, RT, GR, etc.)		Sec. 33, T-27-N, R-8-W
	6728 Gr.		San Juan New Mexico
16.	Check Appropriate Box To Indic		
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIES REPAIR WELL (Other)	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report recompletion or Rec	REPAIRING WELL ALTERING CASING ABANDONMENT® Sults of multiple completion on Well ompletion Report and Log form.) ates, including estimated date of starting any ertical depths for all markers and sones perti-
cmt at 56 7-5/8" cs 5/3/67.	Drld to 566'. Ran 176. Cmt Circ. WOC. Drl g set at 2814, cmtd w/33 Ran 216 jts 4-1/2" 10.5 Cmtd w/100 sx cmt. Rel	d out and drld to 2810 30 sx cmt. WOC. Drld & 11.6# csg set at 702 rig 5/3/67. WO Comp.	to TD 7300 on 20 w/stage collar
18. I hereby certify that the		Condon Production Cla	
SIGNED G. A.	For TITLE	Senior Production Cle	PR May 8, 1967
APPROVED BY	TITLE		DATE
1 Cont.	#C I	ations on Reverse Side	roge (Signature)

1 F4le.

*See Instructions on Reverse Side