

6 BLM 1 Southland 1 Kirby Group 1 File  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	5. LEASE DESIGNATION AND SERIAL NO. NM 0553184
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87499	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1848' FSL - 1770' FEL	8. FARM OR LEASE NAME Ojo He He
14. PERMIT NO.	9. WELL NO. 4
	10. FIELD AND POOL, OR WILDCAT WAW - Pictured Cliffs
15. ELEVATIONS (Show whether DF, ST, GR, etc.) 6155' GL	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 32, T 27N, R 13W, NMPM
	12. COUNTY OR PARISH San Juan
	13. STATE NM

RECEIVED

APR 21 1987

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Request permission to plug & abandon the subject well as follows:

1. Plan to fill 2-7/8" OD, 6.5#, J-55, 10V tubing for casing from P.B.T.D. 1369' to surface with 35 sx class "B" neat cement.
2. Plan to install permanent dry hole monument.
3. Plan to fill all pits.
4. Plan to clean well location of all equipment, pipe, junk & trash.
5. Plan to restore surface.
6. Plan to cut off tie-downs.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Sherman S. Dugan*

TITLE

Geologist

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

*ah 2*

TITLE

APPROVED

DATE

4-20-87

DATE

APR 21 1987

AREA MANAGER  
FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

NMOCO