UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and F	Reports on Wells	0 70 1.50	
		5.	Lease Number
	$(i_{i,j})_{i \in I}$	2 14 P	NM-013861
1. Type of Well GAS	Vit. I.	: i	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator			
MERIDIAN OIL		8.	Well Name & Number
3. Address & Phone No. of Operator		•	Grambling A #1A
PO Box 4289, Farmington, NM 87499 (5	305) 326-9700	9.	-
			30-045-23699
4. Location of Well, Footage, Sec., T, R,		10.	Field and Pool Blanco Mesaverde
1850'FNL, 1850'FWL, Sec.21, T-28-N, R-	-o-w, NMPM	11.	County and State
			San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NAT	TURE OF NOTICE. F	EPORT OTHER	DATA
Type of Submission	Type of Actio		
X Notice of Intent Abar	ndonment	Change of Pla	
		New Construc	
	gging Back	Non-Routine Water Shut o	
	ering Casing		
	er - Bradenhead 1		3
13. Describe Proposed or Completed Oper	rations		
It is intended to repair the brader	nhead of the subj	ect well acc	ording to the
attached procedure and well			

		$\int_{\Omega} f(x) dx$	
		192	
	•		
		٨	MAY I G MED THE
		ത്ര	•
		905	
			La.
		÷ .	
14. I hereby certify that the foregoing	g is true and com	crect.	
signed My Stalpuld (ROS3)	Title Regulatory	Administrato	<u>r</u> Date 5/2/96
(This space for Federal or State Office of			
	tle	Date _	APPROVE
CONDITION OF APPROVAL, if any:			APPROT

MAY 0 6 1996

F. DISTRICT MANAGER

Grambling A #1A Blanco Mesaverde NW Section 21, T-28-N, R-8-W Recommended Bradenhead Repair Procedure

- 1. Comply with all NMOCD, BLM and Meridian safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig.
- MOL and RU workover rig. Blow well down. NU 7-1/16" 3000 psi (6" 900 series) BOP with stripping head. Test and record operation of BOP rams. Kill well with 1% KCL water only if necessary. Have wellhead inspected at A-1 Machine if needed.
- 3. Release donut and PU 2-3/8", 4.7#, J-55, tubing (total of 151 jts landed @ 4785', SN @ 4753'). Pick up additional jts of tbg and tag bottom. TOOH. Visually inspect tbg for corrosion and replace bad joints as necessary. PU and round trip 4-1/2" casing scraper, 3-7/8" bit and bit sub to 3697' (50' above top perf).
- 4. TIH with 4-1/2" RBP and set RBP at 3697' (50' above MV perfs). Pressure test casing to 1000 psig. Spot 10' of sand on top of RBP. TOOH with tubing.
- 5. RU wireline unit. Run CBL (with 1000 psig pressure) to determine TOC behind 7" casing. Estimated TOC is 600' per temperature survey. Contact Operations Engineer (R.O.Stanfield 326-9715, Pager 324-2674) for cement squeeze procedure. Notify MOI Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. As much time as possible to the pump time is needed for the Agency to be able to show up for the cement job.
- 6. WOC 12 hrs. Clean out to below squeeze with 6-1/4" mill or bit. Pressure test to 1000 psig. Re-squeeze as necessary.
- 7. TIH with 7" casing scraper to below squeeze. TOH. TIH with retrieving tool on 2-3/8" tubing blowing down with gas or air. Retrieve RBP and TOH.
- 8. TIH with 2-3/8" tubing with a notched expendable check valve on bottom and a seating nipple one joint off bottom. CO to PBTD @ 4844'. Take and record gauges.
- Land tubing near bottom perforation at 4789'. ND BOP and NU wellhead. Pump off expendable check valve and record final gauges. Return well to production.

Recommended: Operations Engineer


Approved 900 4/17/96
Drilling Superintendent

Grambling A #1A

CURRENT

Blanco Mesaverde

1850' FNL, 1850' FWL, NW Section 21, T-28-N, R-08-W, San Juan County, NM Latitude/Longtitude: 36.649017 / 107.688400



<u>Initial Po</u>	Initial Potential		Production History	<u>Gas</u>	<u>Oil</u>	<u>Ownership</u>		<u>Pipeline</u>
Initial AOF: Current SICP:	2047 Mcfd 427 psig	(9/80) (5/93)	Cumulative: Current:	1,184.0 MMcf 276.9 Mcfd	5.1 Mbo 0.0 bbls/d	GWI: NRI: TRUST:	100.00% 86.50% 00.00%	EPNG