<b>E</b> ' > 1	STATE UP NEVV NICE ERGY AND MITIERALS DI			NT
<b>5</b> ,1 <b>4</b>	or tories otterres	Τ		
	DIST # JBUTION			
	SANTA FE			
	FILE	↓_		
	U.S.G.S.			
	LAND OFFICE	1_		1
	OPERAT DR	<u>ا</u>	<u> </u>	1

CONDITIONS OF APPROVAL, IF ANY:

## OIL ONSERVATION DIVISION P. O. BOX 2088

Form C-103 Revised 10-1-78

SANTA FE SANT	A FE, NEW MEXICO 87501	
FILE	•	Sa. Indicate Type of Lesse
U.S.G.S.		State X Fee
LAND OFFICE	•	5. State Oil 6 Gas Lease No.
DPERATOR		See Item 17
SUNDRY NOTICES AND R	EPORTS ON WELLS	
GIO NOT USE THIS USE "APPLICATION FOR PERMIT" IFORK	- C-101; FOR SUCH PROPOSALS.	7. Unit Agreement Name
OIL X WELL X OTHER-	والمستعمل والمستعم والمستعمل والمستعمل والمستعمل والمستعمل والمستعمل والمستع	8, Firm or Lease Name
Name of Operator		State Com
Union Texas Petroleum Corporation		9. Well No.
Address of Operator		1 · · ·
P.O. Box 1290 Farmington, New Mexico	87499	11 E
Location of Well		10. Field and Pool, or Wildcat
	NE South LINE AND 1745	Undes Gallup/Basin Dakota
UNIT LETTER 0 990 FEET PROM TO	4E CINE AND	
East , 16	28N RANGE 9W	
THETOW	HSHIP RAHEE H	
	n (Show whether DF, RT, GR, esc.)	12. County
MINING GR		San Juan (1)1311111
6. Check Appropriate Box T	o Indicate Nature of Notice, Report or	Other Data
NOTICE OF INTENTION TO:	SUBSEQU	ENT REPORT OF:
HOTICE OF MALES		_
	ND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUE AND ABANDONMENT
TEMPORARILY ABANDON		
PULL OR ALTER CASING CHANGE	PLANS CASING TEST AND CEMENT JOS	·
	OTHER	
THE		
7. Describe Proposed or Completed Operations (Clearly state	all pertinent details, and give pertinent dates, incli	uding estimated date of starting any proposed
work) SEE RULE 1103.	•	•
State Oil & Gas Lease No. Gallup:	B-11017-39	
Dakota:	E-6635-1, E-588-2, E-2131-3, B	11-17-35, E-4959-1
Dakota.	[-0055 1, E 500 E, E E101 0, 5.	2, 50, 2 ,555
- 13 January and abandoned a	a fallows:	
The well was plugged and abandoned a	S TOTTOWS:	
OCCEL DID		
RIH w/4½" drill pipe to 2625' RKB.		
Circulate and condition hole.		
Set 1st cement plug from 2625' to 22	75' RKB	
POOH, L.D. drill pipe.	po	# 3 <b>1</b> 8 1 3 <b>4</b>
Set 2nd cement plug from 1710' to 16	10' RKB	
POOH, L.D. drill pipe.	1 2	CON. DN.
Cat and coment plug from 320' to 220		DIST. 3
Set 3rd cement plug from 320' to 220	IND	िकिक्षेत्र के
POOH, L.D. drill pipe.	location after State Com #1E i	s drilled
Will set top plug, marker, and clean	Totalion after State com #11 1.	3 di litted.
	* • • • • ·	
	·	
•		
	A second by allow	
18. I hereby certify that the information above is true and com	plets to the best of my knowledge and betief.	•
1 A C D. 1-f-	,	10/00/00
Ju comser	Engineering Analyst	BATE 12/22/83
WICHED JA. Edwister		
	THE THE PART OF TH	117)
Original Signed by CHARLES GHOLSON	DEPUTY OR A BAS INSPECTOR, DIST.	# MON - 1 1984 _
	# 1 # 1 # 1 # 1 # 1 # 1 # 1 # 1 # 1 # 1	UAIL