Form 3160-5 (June 1990)

or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

PORM APPROVED Budget Bureau No. 1004-0135

/		Expires:	March	31, 1993
5.	Lease	Designat		Social No.

SUNDRY NOTI	CES AN	D REPORT	S ON W	FILS
JUNUNI NUII	ULU 711	D REFORE	3 VII W	

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

SF-080382-A 6. If Indian, Allottes or Tribs Name

Navajo Nation NIP

FARMINGTON DISTRICT OFFICE Swm

RY .

SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation

Type of Well Oil Well Well Other		8. Well Name and No.
Name of Operator		Schwerdtfeger *17* 1R
Marathon Oil Company		9. API Well No.
. Address and Telephone No.		30-045-29008
P.O. Box 552 Midland, Tx. 79702	915-682-1626	10. Field and Pool, or Exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey DUL "T" 1605' FSL & 1135' FEL	escription)	Basin Fruitland Coal
Sec 17, T-77-N, R-11-W		11. County or Parish, State
		San Juan Co., NM
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	٧
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routins Practuring
• •	Casing Repair	Water Stant-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	K Other New well completion	Dispose Water
		(Note: Report results of multiple completion on Wel Completion or Recognistics Report and Las form.
rathon Oil Co. recently completed this 22-94 MIRU PU RIH with bit and scrap le clean with 2% KCI. POOH with work 47-59, 1865-78 with 4/JSPF (111 h OH with PPI tool. Nu Frac valve. Fra /30 sand. Blew well back to pit. Flo	ical depths for all markers and zones pertinent to this work.)* Is new well as per the history summarized beloper to PBTD @ 2034'. Pressure tested casing to string. Ran CBL/CCL/GR PDTD to 180'. Performoles). Using Pinpoint Injection Tool acidized 18 Ctured 1839—1878 with 76,000 gallons 70 quality well to pit to clean up. Cleaned well out to 20 performed to pit to clean up. Cleaned well out to 20 performed to pit to clean up.	ow. to 2500 PSI. Test OK. Circulated ated 5 1/2" casing 1839–42, 139–1878 with 7 1/2% Hcl. lity foamed N2 carrying180,000 034 PBTD. RiH with 2 3/8"
give subsurface locations and measured and true verturathon Oil Co. recently completed this 22-94 MIRU PU RIH with bit and scraple clean with 2% KCI. POOH with work 47-59, 1865-78 with 4/JSPF (111 h OH with PPI tool. Nu Frac valve. Fra /30 sand. Blew well back to pit. Flooduction string. Seating Nipple @ 188	ical depths for all markers and zones pertinent to this work.)* Is new well as per the history summarized belover to PBTD @ 2034'. Pressure tested casing the string. Ran CBL/CCL/GR PDTD to 180'. Performoles). Using Pinpoint Injection Tool acidized 18 ctured 1839–1878 with 76,000 gallons 70 quality of the clean up. Cleaned well out to 200' KBM. Opened well up to frac tank for clear parator. RDMO PU 1-26-94	ow. to 2500 PSI. Test OK. Circulated ated 5 1/2" casing 1839–42, 139–1878 with 7 1/2% Hcl. lity foamed N2 carrying180,000 034 PBTD. RiH with 2 3/8"
give subsurface locations and measured and true verturathon Oil Co. recently completed this 22-94 MIRU PU RIH with bit and scraple clean with 2% KCI. POOH with work 47-59, 1865-78 with 4/JSPF (111 hold with PPI tool. Nu Frac valve. Frac /30 sand. Blow well back to pit. Flo	ical depths for all markers and zones pertinent to this work.)* 8 new well as per the history summarized belover to PBTD @ 2034'. Pressure tested casing to string. Ran CBL/CCL/GR PDTD to 180'. Performoles). Using Pinpoint Injection Tool acidized 18 ctured 1839–1878 with 76,000 gallons 70 qual owed to pit to clean up. Cleaned well out to 200' KBM. Opened well up to frac tank for clear parator. RDMO PU 1-26-94	to 2500 PSI. Test OK. Circulated ated 5 1/2" casing 1839–42, 139–1878 with 7 1/2% Hcl. lity foamed N2 carrying 180,000 034 PBTD. RiH with 2 3/8" in up. Flowed well to frac tank

*See Instruction on Reverse Side

AND AND THE