## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

DISTRICT MANAGER

CHAIDDY MOTICES AND DEDODES ON MELLS	5/Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS	SF 077111
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
Use "APPLICATION FOR PERMIT - " for such proposals	
	7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Well Other	8. Well Name and No.
2. Name of Operator Attention:	Storey C LS # 3
Amoco Production Company Lois Raeburn	9. API Well No.
3. Address and Telephone No.	30045206953
P.O. Box 800, Denver, Colorado 80201	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	S. Bla Aztec Pictured Cliffs
272 TO 200 TT 201 D 214	11. County or Parish, State
850 FSL	San Juan New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE , R	
TYPE OF SUBMISSION TO THE OF ACTION	
Notice of Intent  SEP - 2 1994  Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other  (Note: Report	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water  T results of multiple completion on Well Completion or n Report and Log form. )
Subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*  Amoco Production Company request permission to Plug and Abandon the above mentioned Preapproved, Verbal with Steve Mason, by Carolanne Wyett, 8/18/1994  If you shoul have any questions please contact Carolanne Wyett @ (303) 830-5578	RECEIVED STANDS 29 PM 4: 01 070 FARRINGFON, NM
14. I hereby certify that the foregoing is true and correct  Signed Title Business Assi  (This space for Federal or State office use)	stant Date 08-24-1994
Approved by Title	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fiction

representations as to any matter within its jurisdiction.

	AUG 18 '94 Ø9:36AM AMOCO 12 Facsimile Transmission	TH FLOOR 3038304777	P.1
	16-717-G (3-92)	5 Steve Mason	R Carolanne (1) 10H
		A) m	0 11 5 18 19
	Date Time Sent	DKII)	M arroco
	8/18/94 10:30	Jamin ton	Denuze
i	This transmission a pages	FAX Number	FAX Telephone Number
	consists on	FAX Operator's Number for Confirmation	Voice Telephone Number
J			

Notes:

Thanks for all your help.

## PXA Procedures Storey C LS #3

- Pull out of retainer and spot cement plug to 2720' with 46.696 cuft cement.
- 2. RIH with tbg and cement retainer, set retainer at 1750', squeeze through casing leak at 1800' to 2219' with 174.177 cuft cement. Pull out of retainer and spot cement plug to 900' with 170.340 cuft cement.
- 3. Attempt to circulate to surface through casing leak at 700' to 900' with 150.30 cuft cement. Pull out of hole and fill to surface with 180.360 cuft cement. If unable to circulate perf at 181' and circulate the bradenhead and fill hole to surface.
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Turn over to John Schwartz for reclamation.
- 6. Rehabilitate location according to BLM or State requirements.