

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985
6. LEASE DESIGNATION AND SERIAL NO.
Fed. 082 079508

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back wells. Use "APPLICATION FOR PERMIT" for such proposals.)

NOV 24 1986

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
Jay J. Harris

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

3. ADDRESS OF OPERATOR
801 Ridgecrest Dr., SE, Albuquerque, N. M. 87108

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1650 fr. S - 990' fr. W of Sec. 35, T28N, R10W
NMPM, San Juan County, N. M.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Cole

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Fulcher-Kutz
1650 fr. S & E of Sec. 35
T28N, R10W, NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH
San Juan

13. STATE
N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) Long term Shut in. - 1 yr. ☒

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We are asking for this long term shut in for the above well due to the following:

1. Very intermittent operations allows the well to accumulate fluid and stops production requiring the fluid to be swabbed out at considerable expense. Too much of this is poor economics. We are of the opinion that conditions will improve enough during this year that it will be possible to produce this well at a profit. If this doesn't happen I plan to drill another well in a better location. If I can afford to drill I will probably go ahead with it any way. The old well is still capable of production as the pressures indicate. On the last State Shut in test the Cole well was 200 lbs, and the other three wells on the lease were as follows :

OMLER # 3 - 184 lbs. OMLER # 2 - 185 lbs. and 200 lbs. on the other. It is my firm belief that the present Cole No. 1 will produce commercially if given a half a chance,

Jay J. Harris

18. I hereby certify that the foregoing is true and correct

SIGNED

Jay J. Harris

TITLE Operator

NOV 25 1986

DATE 11 - 19 - 86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL IF ANY

TITLE

DATE

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

WELL		WELL NAME		ACT DATE		WELL LOG CLAIM		FULL DAYS		WELL LOG	
NO	METER					HRS	DAYS	SHUT-IN	CODE	REASON	
8 01	74168	COLE #1									
		ADJUSTMENTS TO WELL LOG:									
				86/09	08/31/86	192	8.0	08	11	SHUT-IN-MARKET REQUIREMENTS	
				86/09	09/08/86	192	8.0	08	11	SHUT-IN-MARKET REQUIREMENTS	
				86/09	09/16/86	144	6.0	06	11	SHUT-IN-MARKET REQUIREMENTS	
				86/09	09/22/86	192	8.0	08	11	SHUT-IN-MARKET REQUIREMENTS	
					TOTAL:	720	30.0				
		CURRENT MONTH WELL LOG									
				86/10	09/30/86	192	8.0	08	11	SHUT-IN-MARKET REQUIREMENTS	
				86/10	10/08/86	192	8.0	08	11	SHUT-IN-MARKET REQUIREMENTS	
				86/10	10/16/86	168	7.0	07	11	SHUT-IN-MARKET REQUIREMENTS	
				86/10	10/23/86	192	8.0	08	11	SHUT-IN-MARKET REQUIREMENTS	
					TOTAL:	744	31.0				

CURRENT MONTH OPERATOR TOTAL: 744 HOURS 31.0 DAYS
 : PLEASE VERIFY THIS REPORT AND IF YOU DO NOT AGREE WITH THE ABOVE REFERENCED DATA, CONTACT BILL LANE (915) 541-2687 WITHIN 30 DAYS.

Information Copy