	4							
SANTA FE			W MEXICO OIL - REQUEST	CONSERVATION FOR ALLOW			Form C-104 Supersedes Old C-10 Effective 1-1-65	1 and C-1
FILE		-		AND			Effective 1-1-03	
U.S.G.S.		AUTHORIZ	ATION TO TR	ANSPORT OH	_ AND NATUR	RAL GAS		
LAND OFFICE		_						
TRANSPORTER		- · 1						
00000000	GAS							
PROPATION OF			•			•		
Cperator C	Frice							
EL PASO I	NATURAL GAS	COMPANY						
Address								
PO Box 99	90, Farmingt	on, MM 87401	L .					
	g (Check proper bo:			Oth	et (Please explair	1)		
New Well		Change in Tra	nsporter of:					
Hecompletion	X.	011	Dry G	las				
Change in Ownersh	h.ip	Casinghead Go	S Conde	ensate				
If change of owne and address of pr								
H. DESCRIPTION	OF WELL AND	LEASE						
Lease Name			Well No. Pool N	ame, Including F	ormation	Kind of		
Lackey B			17 Bas	sin Dakota	l	State, F	ederal or Fee	
Location						_		
Unit Letter	G 23	310 Feet From Th	e_North_L	ne and1550	Feet	From The Eas	t	
	03 -	ownship 28	_	0	****	San Juan		~
Line of Section	21 , 79	waship 20	Range	9	, NMPM,	Dan Juan		County
TIL DESIGNATION	ለ ይ ሞክ ነእናክስካ	TEN OF OF AN	n Nammara e	A S				
III. DESIGNATION Name of Authorize	OF TRANSPOR	TEN OF OIL AND			address to which	approved copy o	f this form is to be s	ent)
III. DESIGNATION Name of Authorize	OF TRANSPOR	TED OF OH. AN			address to which	approved copy o	f this form is to be s	ent)
Name of Authorize	OF TRANSPOR	or Conder		Address (Give			f this form is to be s	
Name of Authorize	d Transporter of Oi	or Conder	nsate 🗀	Address (Give				
Name of Authorize	d Transporter of Oi d Transporter of Co	or Conder	nsate 🗀	Address (Give	address to which			
Name of Authorize	d Transporter of Oi d Transporter of Co il or liquids,	or Conder	or Dry Gas	Address (Give	address to which	approved copy o		
Name of Authorize If well produces of give location of ta	d Transporter of Oi d Transporter of Co il or liquids, inks.	or Conder	or Dry Gas Trup.	Address (Give	address to which	When		
Name of Authorize Name of Authorize If well produces of give location of ta	d Transporter of Oi d Transporter of Co il or liquids, inks.	or Conder	or Dry Gas T	Address (Give	address to which y connected? ing order numbe	When	f this form is to be s	ent)
Name of Authorize If well produces of give location of ta If this production IV. COMPLETION	d Transporter of Oi d Transporter of Co il or liquids, inks. is commingled w DATA	or Condernatinghead Gas	or Dry Gas T	Address (Give	address to which	When	f this form is to be s	ent)
Name of Authorize Name of Authorize If well produces of give location of ta If this production IV. COMPLETION Designate T	d Transporter of Oi d Transporter of Co il or liquids, inks.	or Condernations of Con	or Ery Gas TRup. Rge. her lease or pool	Address (Give	address to which y connected? ing order numbe	When Plug Ba	f this form is to be s	ent)
Name of Authorize If well produces of give location of ta If this production IV. COMPLETION	d Transporter of Oi d Transporter of Co il or liquids, inks. is commingled w DATA	or Condernatinghead Gas	or Ery Gas TRup. Rge. her lease or pool	Address (Give	address to which y connected? ing order numbe	When	f this form is to be s	ent)
Name of Authorize Name of Authorize If well produces of give location of ta If this production IV. COMPLETION Designate T Date Spudded	d Transporter of Oi d Transporter of Co il or liquids, inks. is commingled w DATA	or Condernations of Con	or Ery Gas Trup. Rige. her lease or pool Gas Well Gas Well	Address (Give Address (Give Is gas actual) give comming New Well Total Depth	y connected? ing order numbe	When Plug Bo	this form is to be s	ent)
Name of Authorize Name of Authorize If well produces of give location of ta If this production IV. COMPLETION Designate T	d Transporter of Oi d Transporter of Co il or liquids, inks. is commingled w DATA	or Condernations of Con	or Ery Gas Trup. Rige. her lease or pool Gas Well Gas Well	Address (Give	y connected? ing order numbe	When Plug Ba	this form is to be s	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded	d Transporter of Oi d Transporter of Co il or liquids, inks. is commingled w DATA	or Condernations of Con	or Ery Gas Trup. Rige. her lease or pool Gas Well Gas Well	Address (Give Address (Give Is gas actual) give comming New Well Total Depth	y connected? ing order numbe	When Plug Bo	ck Same Res'v. D	ent)
Name of Authorize Name of Authorize If well produces of give location of ta If this production IV. COMPLETION Designate T Date Spudded	d Transporter of Oi d Transporter of Co il or liquids, inks. is commingled w DATA	or Condernations of Con	or Ery Gas Trup. Rige. her lease or pool Gas Well Gas Well	Address (Give Address (Give Is gas actual) give comming New Well Total Depth	y connected? ing order numbe	When Plug Bo	this form is to be s	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded	d Transporter of Oi d Transporter of Co il or liquids, inks. is commingled w DATA	or Condernations of Con	or Ery Gas Core Twp. Rge. Twp. Rge. her lease or pool Gas Well to Prod.	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas (address to which y connected? ing order numbe Vorkove: Dee;	When Plug Bo	ck Same Res'v. D	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded Pool Perforations	d Transporter of Oid Transporter of Coil or liquids, take. is commingled wat DATA Type of Completi	or Condernations of Con	or Ery Gas Case Case Case Case Case Case Case Ca	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas i	address to which y connected? ing order numbe Workover Dee;	When Plug Bo	ck Same Res'v. D.	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded Pool Perforations HOL	d Transporter of Oid Transporter of Coil or liquids, inks. is commingled w DATA ype of Completi	or Condernations of Con	or Ery Gas Cor Ery Gas Well Cor	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas (address to which y connected? ing order numbe Vorkove: Dee;	when Plug Ba P.B.T.D	ck Same Res'v. Do. Depth Gasing Shoe	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded Pool Perforations HOL	d Transporter of Oid Transporter of Coil or liquids, inks. is commingled w DATA ype of Completi	or Condernations of Con	or Ery Gas Cor Ery Gas Well Cor	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas (address to which y connected? ing order numbe Workover Dee;	when Plug Ba P.B.T.D	ck Same Res'v. D.	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded Pool Perforations HOL	d Transporter of Oid Transporter of Coil or liquids, inks. is commingled w DATA ype of Completi	or Condernations of Con	or Ery Gas Cor Ery Gas Well Cor	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas (address to which y connected? ing order numbe Workover Dee;	when Plug Ba P.B.T.D	ck Same Res'v. Do. Depth Gasing Shoe	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded Pool Perforations HOL	d Transporter of Oid Transporter of Coil or liquids, inks. is commingled w DATA ype of Completi	or Condernations of Con	or Ery Gas Cor Ery Gas Well Cor	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas (address to which y connected? ing order numbe Workover Dee;	when Plug Ba P.B.T.D	ck Same Res'v. Do. Depth Gasing Shoe	ent)
Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded Pool Perforations HOL Installe	d Transporter of Oid Transporter of Coil or liquids, links. is commingled w DATA Type of Completion E SIZE d Intermitte	or Condernations of Con	or Ery Gas Cor Ery Gas Well Cor	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas i	address to which y connected? ing order numbe Workover Dee;	when Plug Ba P.B.T.L Tabing Dept. C	ck Same Res'v. Depth	ent)
Name of Authorize Name of Authorize If well produces or give location of ta If this production IV. COMPLETION Designate T Date Spudded Pool Perforations HOL	d Transporter of Oid Transporter of Coil or liquids, links. is commingled w DATA Type of Completion E SIZE d Intermitte	or Condernations of Con	or Ery Gas Cor Ery Gas Well Cor Ery Gas Well Cor Ery Gas Well Cor Ery Gas Well Cor Ery Gas	Address (Give Address (Give Is gas actual) , give comming) New Well Total Depth Top Oil/Gas i	address to which y connected? ing order numbe Vorkove: Dee; RECORD EPTH SET	when Plug Ba P.B.T.L Tabing Dept. C	ck Same Res'v. Do. Depth Gasing Shoe	ent)

Tubing Pressure Casing Pressure Choke Si: Length of Test Actual Prod. During Test Oil-Bbls. Water-Bbls. Gas - M

OIL CON. COM GAS WELL Actual Prod. Test-MCF/D Length of Test Bbis. Condensate/MMCF Gravity ondist. 3 Tubing Pressure Casing Pressure Choke Size Testing Method (pitot, back pr.)

VI. CERTIFICATE OF COMPLIANCE

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

K. C. McBride Production Engineer
(Title)

October 28, 1968

OCT 3 0 1968

OIL CONSERVATION COMMISSION

BY Original Signed by Emery C. Arnold SUPERVISOR DIST. #3 TITLE .

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out Sections I, II, III, and VI only for changes of owner, well name or number, or transporter, or other such change of condition.

Separate Forms C-104 must be filed for each pool in multiply