



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**  
Governor  
**Jennifer A. Salisbury**  
Cabinet Secretary

**Lori Wrotenbery**  
Director  
Oil Conservation Division

August 8, 2000

Mr. Donald Blair  
Conoco Inc.  
3315 Bloomfield Hwy  
Farmington NM 87499

RE: Lackey B LS 10, G-21-28N-09W, API 30-045-073 ~~22~~

23

Mr. Donald Blair:

The 2000 Packer Leakage Test on the above referenced well does not provide the required information. It is necessary to show a crossover of pressures for the separate zones. This is accomplished by producing the higher-pressure zone until the pressure is below the lower-pressure zone. If the test can not be accomplished in this manner, follow the instructions on the back of the form for a complete test. Conduct the test and submit the required information within thirty days of receiving this letter.

Feel free to call me at 334-6178, ext. 16, if I can be of any help.

Sincerely,

Charlie T. Perrin  
Deputy O&G Inspector  
cperrin@state.nm.us

CTP/mk

xc: CTP File  
Well File