

**SOUTHERN UNION OAS COMPANY**

P. O. BOX 398 • BLOOMFIELD, N. MEXICO 87413

July 2, 1970



Mr. John Watkins  
Aztec Oil and Gas Company  
P O Drawer 570  
Farmington, New Mexico

Dear Sir:

As of July 2, 1970 changes have been made to correct a mix-up between well names of Aztec Reid #7 and Aztec Reid #10. Evidently, the name signs were reversed on these two wells at the time they were being drilled.

The measuring equipment and name signs have been switched to the correct locations:

---

Aztec Reid #7 (Sta. #2483-03) is located NE/4 19-28N-09W  
Aztec Reid #10 (Sta. #2482-03) is located SW/4 17-28N-09W

Southern Union's property records are correct, this was an error at the well locations.

Sincerely,

A handwritten signature in cursive script, appearing to read "Derald Ferrari".

Derald Ferrari  
Measurement Superintendent

gp

cc: Oil Conservation Commission  
Bruno Giovanini  
J. R. Large  
File