Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED		
Budget Bureau No. 1004-0135		
Expires: March 31, 1993		

BUREA	U OF LAND MANAGEMENT		
SUNDRY NOTICES AND REPORTS ON WELLS		5, Lease Designation and Serial No.	
		SF-077111	
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Allottee or Tribe Name	
Use "APPLIC	ATION FOR PERMIT - " for such proposals		
		7 If this as CA Assessment Designation	
		7. If Unit or CA, Agreement Designation	
1 T			
1. Type of Well Oil Well Well Other		8. Well Name and No.	
		STOREY C LS 14	
2. Name of Operator AMOCO PRODUCTION COMPANY Deanne TALLANT		9. API Well No.	
	-ANT DOMEST MEDIUS	3004507351	
3. Address and Telephone No. (303) 830-4040		10. Field and Pool, or Exploratory Area	
P.O. Box 800 Denver, Colorado 80201 (303) 830-4040		BASIN-DAKOTA-GAS	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			
4550	FFL Sec. 22 T 28 N R 9 W	11. County or Parish, State	
1143' FNL 1558'	FEL Sec. 22 I 28 N R 9 W	SAN JUAN NEW MEXICO	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
	TYPE OF ACTION		
TYPE OF SUBMISSION			
	№ 1 Г	Change of Plans	
	Abandonment	New Construction	
Notice of Intent	Recompletion Plugging Back	Non-Routine Fracturing	
Subsequent Report	Cesing Repair	Water Shut-Off	
S 2003edneur vehour	Altering Casing	Conversion to Injection	
Final Abandonment Notice	Other	Dispose Water	
	(Note: Re	sport results of multiple completion on Well Completion or etion Report and Log form. }	
13. Describe Proposed or Completed Operations	(Clearly state all pertinent details, and give pertinent dates, including estimated date of start	ting any proposed work . It well is directionally diffied, give	
subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* PLEASE SEE ATTACHMENT FOR PROCEDURE.			
PLEASE SEE ATTACHMEN	11 FOR PROCEDURE.		
		O 10	
		EE CLO	
	المنافقة الما والمنافقة الما والمناف	7.0	
	-1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -	1 3 B	
	and the second		
	my many my		
	01.00% 20%	2 = 8	
	Approved as to place to be well bore.		
	Liability under bond is retained until	07 NM	
	surface restoration is completed.		
	Antigon indicators in antibution.		
IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT DEANNE TALLANT (303) 930-5427.			
IF TOO HAVE ANT GOES	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		

TALLY TBG OUT OF HOLE. PULL 5400' SD. TOH W/ 2-3/8 TBG. TIH W/ SCRAPER TO 6970'. TST TBG TO 1000#. DID NOT TST. LAY DWN 6 JTS. TST OK. TIH W/ PKR SD @ 4900'. TIH. SET PKR @ 6747'. PMP WTR INTO PERFS TO EST RATE. TST CSG. DID NOT HOLD. TOH. LEAK @ 30'. TIH W/ RET SET @ 6747'. PULL OUT OF RET. TST CSG. OK. CIRC HOLE CLEAN. SQUEEZE PERFS W/ 85 SX, SPOT 4 SX ON TOP OF RET. SPOT PLUGS @ 5796-5896', 4040-3940', 2478-2378', 2128-2028'. PERF W/ 2 SHOTS @ 1562'. COULD NOT PMP INTO. SPOT CMT PLUG ACROSS PERFS TO 1380'. PERF W/ 2 SHOTS @ 1380'. COULD NOT PMP INTO. (VERBAL APPROVAL FROM LEN BIXLER/BLM). PMP ON PERFS @ 1380' TO 2000#. WOULD NOT CIRC. PMP 83 SX CMT PLUG FROM 1380-285'. PERF W/ 2 SHOTS @ 270'. PMP 21 SX CMT TO SURF. SD NDBOP. CUT OFF WELL HEAD. FILL CSG W/ CMT TO SURF. WELD ON P&A MARKER. RDMOSU.

3 HER 25 / 21 H : 0