COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBNIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Lease No. 077363
Unit J. C. Devideon

SUNDRY NOTICES AND REPORTS ON WELLS

	NTION TO DRILL		SUBSEQU	ENT REPORT OF	WATER SHUT-OFF		
	NTION TO CHANGE PLANS.				SHOOTING OR ACID		
	NTION TO CHANGE PEANS. NTION TO TEST WATER SH				ALTERING CASING		
	NTION TO RE-DRILL OR RE				REDRILLING OR RE		
	NTION TO RE-DRILL OR ACID		1 11		ABANDONMENT		
	NTION TO SHOOT ON ACTER		11		STORY		_
	NTION TO POLE OR ALTER INTION TO ABANDON WELL						
IOTICE OF INTE	ATTOR TO ADMINDUM WEEK						<u></u>
	(INDICATE ABOVE	BY CHECK MARK	NATURE OF RE	PORT, NOTICE	, OR OTHER DATA	A)	
				ecember 5	2	1	9_4
PA m	is located	268.		and 990		line of sec	21
(14 Bec. a)	nd Sec. No.)	(Twp.)	(Range)	(M)	ridian)		
nts Cano		San J	han		Non Nex	100	
	rield)	(Cou	nty or Subdivision)		(State or 1	Territory)	
ne elevation	of the derrick floo	or above sea	level is	ft.			
			AILS OF W				
	of and expected depth indicate muddling jo	s to objective bs,cementing	sands; show spoints, and all	sizes, weights other impor	ant proposed w	proposed cas ork)	ings;
Orill with Set 125 for Set 5-1/2 sand come	of and expected depth indicate muddling jo h rotary tools est 9-5/8 inch inch 0. D. 17/2 nted with 100 a with cable tool	to top of O. B. 104	sands; show spoints, and all	sizes, weights other impor	ant proposed w d, g commuted	to surfac	٠.
Fill with the second community of the second community of the second community of the second complete of the secon	h rotary tools est 9-5/8 inch inch 0. D. 17/ nted with 100 a with cable tool	to top of O. D. hof Sals make.	points, and all Pictured Sals. Gree Scaning	sizes, weights other impor	d, g commted string on	to surfac Pictured	Cls.1
Fill with Set 125 f. Set 5-1/2 cand come complete to the set of th	h rotary tools est 9-5/8 inch inch 0. D. 17/ ented with 100 a with cable tool and that this plan of as may be commence	to top of O. D. hof Sals. J.	sands; show spoints, and all sales. Gree Scaring spoints and all sales. Gree Scaring spoints are spoints as a second sales. Gree spoints are spoints as a second spoints are spoints are spoints are spoints.	cizes, weights other impor	d, g commted a string on	to surfac Pictured	e. Cli
First Section of the	indicate muddling jo h rotary tools est 9-5/8 inch inch 0. D. 17/ nted with 100 a with cable tool and that this plan of as may be commence	to objective bs, cementing to top of O. B. 101 Sals. June work must read.	sands; show spoints, and all sales. Gree Scaring spoints and all sales. Gree Scaring spoints are spoints as a second sales. Gree spoints are spoints as a second spoints are spoints are spoints are spoints.	cizes, weights other impor	d, g commted a string on	to surfac Pictured	Cli
Fill with Set 125 f. Set 5-1/2 cand come complete to the set of th	h rotary tools est 9-5/8 inch inch 0. D. 17/ ented with 100 a with cable tool and that this plan of as may be commence	to objective bs, cementing to top of O. B. 101 Sals. June work must read.	sands; show spoints, and all sales. Gree Scaring spoints and all sales. Gree Scaring spoints are spoints as a second sales. Gree spoints are spoints as a second spoints are spoints are spoints are spoints.	cizes, weights other impor	d, g commted a string on	to surfac	Cli