Original + 2

STATE OF NEW MEXICO ENERGY and MINERALS DEPARTMENT

Hour, date shul-in



ST ENERGY	and MINE This for be used to packer to	NEW MEXICO :RALS DEPARTME m is not to for reporting letting to the mexico of the mexic	NORTHWEST NE	ONSERVATIO			()[][] E TEST	. G(20 1. DN. 1971. 3	DIV.	Page 1 ed 10/01/78	
Location			NC								(PM)	
		NAME OF RESERVO		TYPE OF P	NOO.	M	ETHOD OF P	ROO.		PROD. MI (The. or	EDIUM	
Upper Completion Lower	Completion PICTURED		D CLIPP	GAS		FLOW				TBG		
Completion MESA VEI		RDE	GAS		PLOW				TBG			
			PRE-FLO	W SHUT-IN P								
Upper Completion	Hour, date s		Length of time shut-		SI press. pei	146				NO		
Lower Hour, date shul-in Completion 05_18_9		shul-in	Length of time shul-		17						17 (Yes or No)	
<u> </u>				FLOW TEST	NO 1							
Commenced	f at thour, da	te) #	05_21_98			ducing (Upp	er er Lower)	. T.C	WER			
TIME (hour, date)		LAPSED TIME	PRESS Upper Completion		PROD.	ZONE	REMARKS					
	9_98_	1-DAY	141	147			BOTT	7.70	NES_	SHUT I	N	
05-2	0-98	2-DAYS	143	161	ļ		BOTI	I ZC	NES S	SHUT I	N	
.05-2	1_98_	3_DAYS	146	172			воті	ı zc	NES S	SHUT_I	N	
.05-2	2-98	1_DAY	147	38	ļ		LOWI	<u> </u>	ONE	PLOWIN	G	
-05-2	3_98	2-DAYS	147	38	<u> </u>		LOWI	ZR_ 2	ONE	PLOWIN	<u> </u>	
Oil:			D based on MCFF		(Orifice	or Meter						
Upper	Hour, date	shut-in	Langth of time shut	-in	Si press. pe	49		8	labilized? (1	fee or No)		
Completion	1		the second selection of the second	<u> </u>	81 27200 20	J-0		3	Labilized?	res or No)		

Length of time shut-in

\$1 press. pelg

FLOW TEST NO. 2

immoneed at Sheur, (de10) # #		TEOW TEST				
TIME	TIME LAPSED TIME		ISURE	Zone producing (Up)	AF OF LOWERS		
flour, detel	SINCE * #	Upper Completion	Lewer Completion	PROD. ZONE TEMP.	REMARKS		
oduction rate o	during test						
il:	ВОРГ) hased on	DLI. :-	••	Grav GOR		
us:		MCFI	PD: Tested thru	(Orifice or Merer)	Grav GOR :		
marks:				(Oldice of Meter)			
			·				
							
sereby certify th	hat the informatio	n herein containe	d is true and cor	nulete to the bee	of my knowledge.		
neous d	JUL	2 6 1000		apiete to the per	or my knowledge.		
oproved New Mexico O	il Conservation Di	2 6 1998	_19 0	perator /	CONOCO INC		
/	Conscivation D) ARIOH		_ domotout	-		
\sim /			_,				
Cho	Muser TY OIL & GAS INSP	rin	•	de field Produc	/		

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the rubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.
- At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rare of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 3. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.
- Flow Test'No. 2 shall be conducted even though no leak was indicated during Flow.
 Frocedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except

- that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.
- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at farteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least rwice, once at the beginning and once at the end of each test, with a dendweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 13 days after completion of the test. Tests shall be filed with the Astet District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packer Leskage Test Form Revised 10-01-78 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).