UNITED STATES Form 3160-5 FORM APPROVED June 1990) Budget Bureau No. 1004-0135 DEPARTMENT OF THE INTERIOR Expires: March 31, 1993 **BUREAU OF LAND MANAGEMENT** 5. Lease Designation and Serial No. NM-020498 **SUNDRY NOTICES AND REPORTS ON WELLS** 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA. Agreement Designation SUBMIT IN TRIPLICATE Type of Well Oil Well X Gas Well 8. Well Name and No. 2. Name of Operator Ohio Government Well No. 2-E Marathon Oil Company 9. API Well No. 3 Address and Telephone No. 30-045-24334 10. Field and Pool, or Exploratory Area P.O. Box 552 Midland, Texas 79702 (915)682-1626 4 Location of Well (Footage, Sec., T., R., M., or Survey Description) Basin (Dakota) 11. County or Parish, State 1965 FSL & 955 FWL; Section 15, T-28-N, R-11-W San Juan County, NM 12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Change of Plans Other Temporarily Abandon Dispose Water ee: Report resu 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, red and true vertical depths for all markers and zones pertinent to this work.)\* 1) MIRU PU. ND Wellhead. Install & test BOPS. POOH w/production equipment. 2) TIH/CIBP. Set CIBP @ 6030'. Dump bail 5 sacks cement. Test casing from surface to 6030' to 500 psi. Hold pressure & record for 30 minutes. Release pressure. 3) ND BOPS & install wellhead. RD PU. MOL. THIS APPROVAL EXPIRES OCT 0 1 1993 OIL CON. DIV.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully a representations or agency of the United States any false, fictitions or fraudulent statement or representations as to any matter within its jurisdiction.

## \*See Instruction on Reverse Side

F/18000 GALS & 23000# 20/40 SD. DRILLED OUT RETAINER & BRIDGE PLUG. WELL WOULD NOT FLOW. SET CEMENT RETAINER @ 6245' IN JANUARY, 1981. WELL FLOWED @ 161 MCFPD, 1/2 BCPD, & 2 BWPD. WELL WAS PLACED ON LINE IN JULY, 1983. WELL FLOWED FOR 30 MINUTES AND DIED. COULD NOT SWAB THE WELL TO FLOW.