Budget B	ureau N	o. 42-H	359.
Approval	expires	12-31-6	0.

	FOFE (A)	oril 19	52)	
I				
	0			

## (SUBMIT IN TRIPLICATE)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Indian Agency			
Jicar	علاا		
Allottee			
AINCEN			
Lease No			
Contract	To.	29	

NOTICE OF INTENTION TO REDRILL OR REPAIR WELL SUBSEQUENT REPORT OF REDRILLING OR REPAIR	NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUPPLEMENTARY WELL HISTORY
SUBSEQUENT REPORT OF ALTERING CASING.	NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.	SUBSEQUENT REPORT OF ALTERING CASING

The elevation of the derrick floor above sea level is \_\_\_\_\_ft.

(Field)

## DETAILS OF WORK

(County or Subdivision)

(Meridian)

(State or Territory)

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Perforated 5-1/2" casing 3606-10' and 3614-18'.

Rio Arriba



		iting by the Geological Survey before operations may be commenced.
Company	Oulf oil corporation	
Address	P. O. Box 2097	ORIGINAL SIGNED BY B. L. ROBERTSON
	Beaver	Ву
	Colorado	Title Division Clerk