/Form Approved.					
	Budget	Bureau	No.	42-R14	24

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424		
UNITED STATES	5. LEASE 2.04. 2.05.		
DEPARTMENT OF THE INTERIOR	SF 077978-A		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME		
1. oil gas . P & A	Douthit 2-21 1 2		
well well other ran	9. WELL NO.		
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	10. FIELD OR WILDCAT NAME A TAMA		
3. ADDRESS OF OPERATOR	tindesignated Amarito Mallin		
P 0 Box 208, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA 출발표를 함 호텔 기준 Sec. 33 T28N R13W 축 문학교수		
AT SURFACE: 990' FSL - 990' FEL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan Russe SNM Sugar		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO		
	15 ELEVATIONS (SHOW DF, KDB, AND WD)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT	304 D.F.		
REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF THE PORT	(1) 10년 (1) 1		
FRACTURE TREAT	(NOTENBAport lesults of multiple completion or zone SUN change on Form 9–330.)		
REPAIR WELL	(NOTE (Report results of multiple completion or zone		
PULL OR ALTER CASING The state of the stat	GICAL N. M. Change on Form 9-330.)		
MULTIPLE COMPLETE	TON THE PARTY OF T		
ABANDON*			
(other)			
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is defined as a starting any proposed work. 	firectionally drilled, give subsurface locations and		
measured and true vertical depths for all markers and zones pertinen	nt to this work.)*		
Plugged and abandoned well as per amended a	and approved request for approval		
to abandon, dated 12-6-82, as follows:			
1 Cat Dakan asment waterings at 5225			
1. Set Baker cement retainer at 5335 5548' with 35 sx 41.3 cu.ft. ceme			
2. Spotted 12 sx (14 cu.ft.) cement	plug 3800' to 3695		
3. Spotted 12 sx (14 cu.ft.) cement	nlug 23881-tő 22835 - az desze		
5. Spotted 12 3x (14 cu. 12.) Cement	5 2 2 3 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		
4. Shot 5½" casing off at 1465'. Pu	ulled same. 프로마스 이 등을 생각하는		
51	continued on revense		
Subsurface Safety Valve: Manu. and Type	Set @Ft.		
18. I hereby certify that the foregoing is true and correct Petroleum Eng	inger 3-17-83		
SIGNED Thomas A. Dugan TITLE	TO PARE TO THE PROPERTY OF THE		
(This space for Federal or State of	APPROPRIED AS AMENDER		
APPROVED BY TITLE	JAN 1 4PM 5		
CONDITIONS OF APPROVAL, IF ANY:	UAN 1 4 1385		

Approved as to plugging of the well pore. Liability under bond is retained until surface restoration is completed.

OIL CON. DIV. DIST. 3

JAN 1.01985 Vs. J. Stan McKee M. MILLENBACH AREA MANAGER

DUGAN PRODUCTION CORP. Douthit #1

- 5. Spotted 19 sx cement plug (23 cu.ft.) 1515 to 1415'.
- 6. Spotted 16 sx cement plug (19 cu.ft.) 1300 to 1245'.
- 7. Spotted 15 sx cement plug (17.7 cu.ft.) from 230 to 180'.
- 8. Spotted 10 sx cement plug at surface and installed dry hole marker.
- *Note #1 9.2#/gal. drilling mud left between all plugs.
- **Note #2 "Deadman" anchors cut off below ground level.
- ***Note #3 Tank will be moved and location restored at a later date.

WORK PERFORMED 3-10 thru 3-15-83.