

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM MAIL ROOM

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

OCT 11 PM 2:32
W.D. FARMINGTON, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BHP PETROLEUM (AMERICAS) INC.

3. Address and Telephone No.

P.O. BOX 977 FARMINGTON, NEW MEXICO (505) 327-1639

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

87499
990' FNL AND 892' FEL
NE/NE SEC.31, T28N, R12W

5. Lease Designation and Serial No.

1-149

IND-8478

6. If Indian, Allottee or Tribe Name

NAVAJO

7. If Unit or CA, Agreement Designation

GALLEGOS CANYON UNIT

8. Well Name and No.

NO. 49

9. API Well No.

30-045-07076

10. Field and Pool, or Exploratory Area

BASIN FRUITLAND COAL

11. County or Parish, State

SAN JUAN, NEW MEXICO

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☒ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1.) Log well from casing shoe to surface to locate Fruitland Coal interval.
- 2.) Production test the Pictured Cliffs; if productive (25 MCF or more) set an RBP @ approximately 1,270'. If unproductive, set a CIBP @ same depth.
- 3.) Test casing and RBP or CIBP to 500 psi.
- 4.) Perforate the Fruitland Coal with 4 JSPF.
- 5.) Fracture stimulate w/a minimum of 40,000# of sand.

B.O.P.E. will consist of a 2000# preventor equipped w/pipe rams for the workstring, blind rams, and a non-rotating stripper head.

14. I hereby certify that the foregoing is true and correct

FRED LOWERY

Signed

Title

MANAGER FIELD OPS.

09-14-95

Date

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

OCT 12 1995

APPROVED

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

NMOC

Certificate Number