

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRIPLICATE*
(Other instructions on re-verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

ME 99979

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

Southeast Cba Cba Unit

8. FARM OR LEASE NAME

9. WELL NO.

34

10. FIELD AND POOL, OR WILDCAT

Cba Cba Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

NW/4 Section 22,

T-28-N, R-13-W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
501 Airport Drive, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface
1980' FWL & 1980' FWL, Unit 'F'

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GL 6061', RDB 6072'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) **Plug Back**


REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The following work was performed on subject well.

1. 4-1/2" bridge plug set at 5716'.
2. 2-3/8" tubing run with 4-1/2" tension packer set at 5652'.
3. Pump and rods run to test productivity.
4. As a result of no oil production, pump and rods have been pulled and the well shut in.



RECEIVED
DEC 4 1968
U. S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct
Signed By: **G. W. Eaton, Jr.** TITLE: **Area Engineer** DATE: **December 3, 1968**

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to abandon a well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, instructions on Federal land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing-pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.