

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth set _____
Adapters—Material _____ Size _____
Saker Type "K" CI cement retainer set at 5800'.

SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out
None						

TOOLS USED **PBT 5800'.**

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
Cable tools were used from **surface** ~~for completion.~~ feet to _____ feet, and from _____ feet to _____ feet

DATES

_____, 19____ Put to producing _____, 19**59**
The production for the first 24 hours was **52** barrels of fluid of which **100** % was oil; _____ %
emulsion; _____ % water; and _____ % sediment. Gravity, °Bé. **21 38.8**
If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____
Rock pressure, lbs. per sq. in. _____

EMPLOYEES

~~Exeter Oil Co. - 42~~ _____, Driller _____, Driller
~~Rota Cons Oil Field~~ _____, Driller _____, Driller
~~Operator Co. - 67~~

FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
			S-LOG TOPS
1030	1946	916	Pictured Cliffs
1946	3627	1681	Cliffhouse
3627	3855	228	Pt. Lookout
3855	4745	890	Mancoes
4745	5210	465	Gallup
5210	5582	372	Sanaskee
5582	5640	58	Greenhorn
5640	5690	50	Graneros
5690	5884	194	Dakota
5884	5904 TO	20	Morrison

AT THE END OF COMPLETE DRILLER'S LOG, ADD GEOLOGIC TOPS. STATE WHETHER FROM EL OR SAMPLES.

