Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED					
Budget Bureau No.	1004-0135				
Expires July 31,	1996				

5. Lease Serial No.

M-020501	M-	0	20	5	0	1
----------	----	---	----	---	---	---

Do not use this form for abandoned well. Use For	6. If Indian, Allottee or Tribe Name		
	Other structions on reverse side	7. If Unit or CA/Agreement, Name and/or N	
1. Type of Well Oil X Gas Well Other 2. Name of Operator Marathon Oil Company 3a. Address P.O. Box 2490 Hobbs, NM 88240 4. Location of Well (Footage, Sec., T., R., M., or Survey Descri	APR 2000 RECOVED 3b. Phone No. (include area code) 505 393-7106	8. Well Name and No. Ohio C Government 1 9. API Well No. 30-045-27726 10. Field and Pool, or Exploratory Area Basin Fruitland Coal	
UL M, Sec. 26, T-28-N, R-11-W 1285' FSL & 895' FWL	The state of the s	11. County or Parish, State San Juan. NM	
12. CHECK APPROPRI	ATE BOX(ES) TO INDICATE NATURE OF NOTICE, REF		
TYPE OF SUBMISSION	TYPE OF AC		
Notice of Intent X Subsequent Report	Acidize Deepen Pro	duction (Start/Resume) Water Shut-Off lamation Well Integrity	
Final Abandonment Notice	Change Plans Plug and Abandon Ten	omplete X Other Add Pay sporarily Abandon and Stimulate er Disposal	
Attach the Bond under which the work will be per following completion of the involved operations. If testing has been completed. Final Abandonment Nodetermined that the final site is ready for final inspection 2/18 MIRU pulling unit. POOH w/p 1629'. POOH. RIH w/RBP, set 2/20 Sand frac 1558-1618 w/48,09 set at 1545'. POOH. Load & SPF, 64 holes. Pump 500 gal 2/21 Pump 1000 gals 15% acid. Sa 20/40 sand. Open well to fl 2/22 RIH w/bit & dc's. Tag sand 2/23 RIH, tag sand at 1613'. Cle 2/24 NU wellhead. RIH w/pump & r 2/25 RD pulling unit. SN at 1543' Btm of tbg 1560'	pump & rods. ND wellhead. NU BOP. POOH w/s at 1498'. Test to 2500 psi, OK. Rel RBP 04 gals Delta 140 w/sandwedge containing test, OK. Perf 1425-27, 1449-52 1489-92 is 10% acid. RIH w/tbg, tag CIBP at 1545' and frac 1424-1518 w/17,640 gals Delta 140 owback tank. at 1434'. Clean out to 1545'. DO CIBP at ean out to 1632' (PBTD). POOH. Run after	to vertical depths of all pertinent markers and zones, red subsequent reports shall be filled within 30 days a new interval, a Form 3160-4 shall be filled once mation, have been completed, and the operator has tbg. RIH w/bit & csg scraper to POOH. 100,000# 20/40 sand. RIH w/CIBP, 1498-1500, 1503, 1514-18 w/4, POOH. 1545. Clean out to 1625.	
4. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Kelly Cook	Title Records Proces	SOF	
Kolly Brok	Billy Appl Date 3/2/00		
THIS	SPACE FOR FEDERAL OR STATE OFFICE USE		
Approved by	Title	ACUTATED FOR RECORD	
Conditions of approval, if any, are attached. Approval of sertify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations thereon.	this notice does not warrant or those rights in the subject lease	4AR 2 8 2000	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any Talse, licitious or fraudulent statements or representations as to any matter within its jurisdiction.