

16--43094-4



REF: RE SERVICES INC. - DENVER, CO., ITEM TO 6009, AND NORTON ITEM TO 6009.
CROSS: NONE

SECRET

Promo w/147,000 gallons of water. BD 1950¢, IP 1300¢, IN 2250¢, AP 1850¢, AT 1550¢, standing 250¢. In before balls 59 balls/min - need 150 rubber balls, etc in

Part w/3 photos per foot, 6008-04, 5978-12, 5951-18, 5942-08, 5904-5882, 5868-54, 5780-76, 5766-62, 5652-46, 5550-50, 5500-14, 5478-68.

It is of the greatest importance to have a complete history of the well. Please state in detail the dates of redrilling, together with the reasons for the work and its results. If there were any changes made in the casing, state why, and if any casing was "sinkerected" or left in the well, give its size and location. If the well has been dynamited, give date, size, position, and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position, and results of pumping or bailing.

HISTORY OF OIL OR GAS WELL

16-43084-2 U. S. GOVERNMENT PRINTING OFFICE

[illegible]