Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED			
Budget Bureau No.	1004-0135		
Business March 2	1 1002		

 Expires:	March 31,	1993	
			_

5.	Lease	Designation	and	Serial	No.
SF-	0784	10			

6. If Indian, Allottee or Tribe Name

SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well		San Juan 29-5 Unit
Oil X Gas Other		8. Well Name and No.
2. Name of Operator		SJ 29-5 Unit #19
Phillips Petroleum Company	-	9. API Well No.
3. Address and Telephone No.	NN 07401 FOE FOO 2454	30-039-07707
5525 Highway 64, NBU 3004, Farming 4. Location of Well (Footage, Sec., T., R., M., or Survey D		10. Field and Pool, or exploratory Area
975' FNL & 1770' FEL	escription)	Blanco Mesaverde
Section 6, T29N, R5W		11. County or Parish, State
Section 6, 123A, Row		Rio Arriba, NM
12. CHECK APPROPRIATE BOX(s	S) TO INDICATE NATURE OF NOTICE, REPORT,	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
_	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other Trouble shooting	_ Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	l pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work.)*	g any proposed work. If well is directionally drille
dated 2/18/97). While attempting t	to the existing Mesaverde zone back in Febru to put well on line, noted loss of casing and I in an attempt to located and fix the problem	tubing pressure. See
7	HIC AGA ADVOL EXPINED JAN 0.1 1998	OIL COMO DINGO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Regulatory Assistant

Title

(This space for Federal or State office use)

Approved by ________/S/ Duane W. Spencer

Approved by

Conditions of approval, if any:

San Juan 29-5 #19 SF-078410; 975' FNL & 1770' FEL, Sec. 6, T29N, R5W, Rio Arriba County, NM

Procedure used to determine downhole problem and correct.

8/19/97

MIRU Big A #7. ND WH & NU BOPs. Test - OK. MIRU wireline & RIH - found tubing stuck @ 4755'. GIH w/chemical cutter & cut tubing @ 5374 & 4730'. POOH w/tubing. NU bottomhole assembly. Wash over fill to packer @ 4734'. COOH. NU overshot. GIH w/overshot & recovered #1 fish (tubing). Fish #2 left in hole. RIH & set RBP @ 4370'. Ran GR-CCL-CBL. No cement behind 5-1/2" casing from 4360' to liner top @ 3852'. TOC @ 3650'.

RIH & set packer & tested casing to isolate leak. Leak found in 7-5/8" casing from 2830' to 1850'. BJ spotted 30 bbls cement (168 cuft) Class B neat from 2817' - 2181'. PUH & spotted 30 bbls (168 cf) Class B neat from 2181' to 1546'. PUH & reversed 1 bbl cement to pit. PUH & closed pipe rams & well. Displace 10.5 bbls in 1 hr. Final hesitation squeeze pressure 500 psi. RD BJ. WOC 12 hrs. Load hole w/27 bbls KCL water & PT to 500 psi. Bled to zero in 10 min. RIH w/bit & tagged hard cement @ 1987'. PT & found hole. Drilled out remaining cement and ran GR-CCL-CBL from 3950' to surface.

RIH w/squeeze gun & perf'd 6 holes @ 3400' at top of coal. COOH. RIH w/packer & set @ 2977'; RU BJ & ran test to establish injection rate. Pumped 2 bbls water ahead & then pumped 60 sx (12.7 bbls) Class B cement w/2% CaCl₂. Displaced with 27 bbls water. PT to 1000 psi - held -OK.

Release packer & COOH to 2027'. Reset packer & test below packer to 500 psi. No bled off. Good test. Load annulus & test casing to 500 psi. Bled down to 0 in 10 min. Released packer & COOH.

GIH w/2-3/8" tubing OE to 1960'. RU BJ to spot cement plug across leak. Pumped 10 bbls water ahead and pumped 6 bbls cement (30 sx Cl B w/1% $CaCl_2$ -35.4 cf). Displaced w/6.5 bbls water. PUH 3 stands. Reversed circ to pit 1/2 bbl cement. Hesitate 1.3 bbls cement into leak to 500 psi. Left 500 psi well.

RIH w/bit & tagged cement @ 1864. Drilled out to 1960' & circ. clean. PT casing to 500 psi - no bled off - good test. RIH & drilled out cement to 3390'. Circ. hole clean. Drilled 50' & PT to 390 psi - lost 110 psi in 10 min. GIH w/7-5/8" packer to 2977'. PT down tubing & backside, no test. COOH w/packer & SI. GIH & retreived RBP. RIH w/mills and milled down 8' to 5376' over top of packer (fish #2). COOH w/packer. Cleaned out to PBTD @ 5964'. Circ hole with air. RIH w/5-1/2" Baker R3 packer, 2-/38" tubing. Set tubing @ 5807' and R-3 packer set in 5-1/2" liner @ 3868'. Rig down and released rig 9/16/97.

Note: Since the casing failed the integrity test a packer was placed in the hole temporarily. Phillips would like to flow test the Lewis Shale to determine if it is feasible to spend anymore money trying to repair the casing. If it is determined to be economical the casing will be repaired. If it is not the well will be plugged and abandoned.

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
Budget Bureau No. 1004-0135

Expires:		March 31,		1993	
	-				

DIDEALOR	LAND MANAGEMENT	Expires: March 31, 1993
BUREAU OF	Lease Designation and Serial No.	
SUNDRY NOTICES A	SF-078410	
Do not use this form for proposals to dril	6. If Indian, Allottee or Tribe Name	
Use APPLICATION FOR	PERMIT - " for such proposals	
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well		San Juan 29-5 Unit
Oil X Gas Other		8. Well Name and No.
2. Name of Operator		
Phillips Petroleum Company		SJ 29-5 Unit #19
3. Address and Telephone No.		9. API Well No.
5525 Highway 64, NBU 3004, Farming	top NM 97401 FOE FOO 2454	30-039-07707
4. Location of Well (Footage, Sec., T., R., M., or Survey D	ton, NM 87401 505-599-3454	10. Field and Pool, or exploratory Area
	escription)	
975' FNL & 1770' FEL		Blanco Mesaverde
Section 6, T29N, T5W		11. County or Parish, State
		Rio Arriba, NM
12. CHECK APPROPRIATE BOX(s	s) TO INDICATE NATURE OF NOTICE, REPOR	
Description of the contract of	TO MENORIE TO NOTICE, HELF ON	I, ON OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTIO	N
Notice of Intent	Abandonment	Change of Plans
Subsequent Report	Recompletion	New Construction
outsiquent report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X OtherTrouble Shooting	
	the other Trouble Shouting	Dispose Water (Note: Report results of multiple completion on Wel
	pertinent details, and give pertinent dates, including estimated date of sta	Completion or Recompletion Report and Log form.)
dated 2/18/97). While attempting t Plans are to locate the problem and	to the existing Mesaverde zone in February o put well on line, we noted a loss in casif a casing leak is indicated, perforate sement to correct any problems found.	ing and tubing pressure
14. I hereby certify that the foregoing is the and correct	2001	
Signed Taloy Clusion	Title Regulatory Assistant	
(This space for Federal or State office use)		
Approved by /S/ Duane W. Spences	Title	OCT 2.2 1997
Conditions of approval, if any:		Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.