

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY


SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME San Juan 29-6 Unit
2. NAME OF OPERATOR El Paso Natural Gas Company		8. FARM OR LEASE NAME San Juan 29-6 Unit
3. ADDRESS OF OPERATOR Box 990, Farmington, New Mexico		9. WELL NO. 93
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650'8, 1075'W		10. FIELD AND POOL, OR WILDCAT Basin Dakota
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T-29-N, R-6-W N.M.P.M.
15. ELEVATIONS (Show whether DF, AT, ON, etc.) 6396' GL		12. COUNTY OR PARISH MURIO ARRIBA
		13. STATE New Mexico



16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☒	REPAIRING WELL	☐
FRACTURE TREATMENT	☒	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

On 5-13-67 spudded well, drilling surface hole.

On 5-14-67 Ran 10 joints 9 5/8", 32.30#, H-40 casing (318.45') set at 332' w/200 sacks cement circulated to surface. W.O.C. 12 hours, tested w/600#/30 Min. O. K.

6-6-67 T. D. 7786'. Ran 31 joints 4 1/2", 11.6# and 208 joints 4 1/2", 16.5# J-55 casing, total of 239 joints (7776') set at 7786'. Float collar at 7749', second stage tool at 5665', third stage tool at 3405'. Cemented first stage w/300 sacks cement, second stage w/155 sacks cement, 3rd stage w/185 sacks cement. W.O.C. 18 hours.

6-8-67 P.B.T.D. 7743'. Tested casing w/4000# O. K. Spotted 500 gal. 7 1/2" BBL. Perf. Dakota 7604-14 w/3 SPT; 7678-85' w/4 SPT. Frac w/50,000# 40/60 mesh, 50,260 gallons of water. Max. pr. 4000#, BOP 1250#, tr. pr. 4000#. I.R. 41.4 BFM. Dropped 1 set of 30 balls, flushed w/5130 gallons of water. ISIP 1800#, 5 Min. 1700#, 30 Min. 900#.



18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by Petroleum Engineer DATE 6-9-67
Carl E. Matthews

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; fluid or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

9-67-831



yd bar ya longin
aweditata 8 no