Form 9-331 (May 1963)

16.

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other in verse side) Instructions

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

GEOL	OGICAL	SURVEY

CHAIDDV	NOTICES	AND	REPORTS	ON	VA/ELIC
SUNDKY	NOHCES	AND	KEPUK 15	ON	MELE?

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use "APPLICATION FOR PERMIT" for such proposals.)

	1	M	18	321			/
6.	1F	IND	IAN,	ALLOTTEE	OR	TRINE	NAM.
				*			

		1
1.		7. UNIT AGREEMENT NAME
WELL GAS X	OTHER	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
	Continental Oil Company	Conoco 29-4
3. ADDRESS OF OPERATOR	•	9. WELL NO.
	152 North Durbin St., Casper, Wyo. 82601	1
4. LOCATION OF WELL (Report I See also space 17 below.)	location clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT
At surface		East San Juan - Dakota
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	1720' FSL, 1510' FEL	SURVET OR AREA
		Sec. 22, T29N, R4W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	7130' GR. 7143' KB	Rio Arriba New Mexic

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:				
EST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING		ABANDONMENT*	
EPAIR WELL		CHANGE PLANS		(Other)		Progress	X
Other)				(Note: Report result	ts of multiple	completion on Well	1

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well spudded 9-7-73. Drilled 12½" hole to 240', set 8 5/8" 24# casing landed at 235', and cemented with 150 sacks Class "A" cement with 2% CaCl₂ - good returns to surface. Bumped plug at 9:15 a.m. 9-8-73.



USGS (6)

NMOCC(2) U.S. Forest Service File(2) 18. I hereby certify that the foregoing is true and correct TITLE Administrative Supervisor DATE _ 12/6/73 SIGNED (This space for Federal or State office use) DATE _ APPROVED BY . CONDITIONS OF APPROVAL, IF ANY: