Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

Expires: March 31, 1993

BUREAU OF 1	5. Lease Designation and Serial No.		
SUNDRY NOTICES AN	NM-03040-A		
Do not use this form for proposals to drill	6. If Indian, Allottee or Tribe Name		
	PERMIT - " for such proposals	1	
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation	
1. Type of Well		San Juan 29-6 Unit	
Oil		8. Well Name and No.	
Phillips Petroleum Company		SJ 29-6 #46A	
3. Address and Telephone No.		9. API Well No. 30-039-21287	
5525 Highway 64, NBU 3004, Fa 4. Location of Well (Footage, Sec., T., R., M., or Survey De	rmington, NM 87401 505-599-3454	10. Field and Pool, or exploratory Area	
Unit D, 940' FNL 7 790' FWL	seripuon	Blanco Mesaverde	
Section 27, T29N, R6W	11. County or Parish, State		
		Rio Arriba, NM	
2. CHECK APPROPRIATE BOX(s	) TO INDICATE NATURE OF NOTICE, REPORT,	OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
X Subsequent Report	Recompletion	New Construction	
Subsequent Report	Plugging Back	Non-Routine Fracturing	
Final Abandonment Notice	Casing Repair	Water Shut-Off	
	Altering Casing  X Other Add pay & stimulate	Conversion to Injection	
	Mad pay & Stillarate	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
Attached is the procedure used Mesaverde formation on the subj	to perforate and stimulate the Lewis Sect well.	Shale zone in the	
	process on the second	• 5 2	
	DEGEIVE	119 F. 110 M.	
	UN JUL 1 4 188/ L		
	O[][ CON. D[] Bists 8	P1	
	Dae no O		
	Amount additional page and in their the way in	,	
4. I hereby certify that the foregoing is true and correct Signed Lees to	Regulatory Assistant	Date 6-19-97	
(This space for Federal or State office use)	400	SEPTED FOR RECORD	
Approved by	Title	JUL 0 9 1997	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the FARMINGTON DISTRICT OFFICE statements or representations as to any matter within its jurisdiction.

\* See Instruction on Reverse Side

## San Juan 29-6 #46A NM-03040-A; Unit D, 940' FNL & 790' FWL Section 27, T29N, R6W; Rio Arriba County, New Mexico

## Procedure used to add Lewis Shale pay to existing MV zone and stimulate.

6/6/97

MIRU Big A #18. Killed well. ND WH & NU BOPs. Test-Ok. COOH w/2-3/8" producting tubing. GIH w/workstirng to 5637' (TD). Cleaned out hole. COOH. RIH & set RBP @ 4514'. Ran GR/CCL/CBL from 4500'-3500'. RIH & perf'd Lewis Shale @ 1spf w/120° pahsing as follows:

4429'-4434'	=	5 holes;	4360'-4365'	=	5 holes;	
4300'-4310'	=	10 holes;	4265'-4270'	=	5 holes;	
4215'-4220'	=	5 holes;	4090'-4095'	=	5 holes;	
4045'-4055'	=	10 holes	4020'-4025'	=	5 holes;	
4000'-4005'	=	5 holes				<b>Total 55 holes</b>

GIH w/4-1/2" packer and set @ 3902'. Load casing w/2% Kcl & test - good test. RU BJ & acidized w/24 bbls of 15% Hcl & 83 ball sealers. Balled off @ 5700 psi. Surged, released packer, knocked balls off and retrieved balls.

RU B&R & RIH w/RTD @ 3955'. RU BJ to frac. Pumped 84,000 gal 2% KCl w/30# gel, pumped 168,200 # 20/40 Arizona sand, & 954,000 scf of N<sub>2</sub> w/70 quality foam. Avg treating pressure 3600#, avg rate 35 bpm. ISIP 1900#. Flowed back immediately on 1/4" choke. Flowed back for 90 hrs. COOH w/RTD. Blue Jet did acoustic survey from 4430'-3900'. Cleaned out with N<sub>2</sub>. COOH w/RBP. Cleaned out casing to TD with air. GIH w/2-3/8" 4.7# J-55 tubing and set at 5601'. Production packer set @ 4524' and "L" sliding sleeve set @ 4236'. ND BOPs and NU WH. Test-Good test. RD & MO. Turned well over to production department.