Form 3160-5

## UNITED STATES

FORM APPROVED				
Budget Bureau No.	1004-0135			
Bynires March	31. 1993			

ine 1990) DEPARTME.	NT OF THE INTERIOR	Expires: March 31, 1993
BUREAU OF	LAND MANAGEMENT	5. Lease Designation and Serial No.
		SF-080662
Oo not use this form for proposals to dril	ND REPORTS ON WELLS  If or to deepen or reentry to a different reservoir.  R PERMIT - " for such proposals	6. If Indian, Allottee or Tribe Name
	T IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Type of Weil	,	San Juan 29-6 Unit
Oil X Gas Well Other  Name of Operator		8. Well Name and No.
Phillips Petroleum Company		SJ 29-6 Unit #11A
Address and Telephone No. 5525 Highway 64, NBU 3004, Farming	gton, NM 87401 505-599-3454	30-039-21386  10. Field and Pool, or exploratory Area
Location of Well (Footage, Sec., T., R., M., or Survey	Description)	l., ., .
Unit D, 1080' FNL & 840' FWL Section 7, T29N, R6W		Blanco Mesaverde 11. County or Parish, State
		Rio Arriba, NM
CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPO	HI, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTI	ON
Notice of Intent	Abandonment	Change of Plans
₩	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
Phai Abandonnion Notes	X Other Add pay and stimul	Conversion to Injection
	Other Add pay and Schiller	ALC Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
See attached for the procedure use Mesaverde formation.	ed to add pay and stimulate the Lewis Shale  AUG 0 6 1999  DIVo	SS JUN 25 F
4. I hereby certify that the foregoing is true and correct Signed  (This space for Federal or State office use)	Title Regulatory Assistant	Date 6/24/99
Approved by	Title	Date —
Conditions of approval, if any:		ACCEPTED FOR RECORD
Title 18 U.S.C. Section 1001, makes it a crime for any pe	erson knowingly and willfully to make to any department or agency of the	United States any false, fictitious or fraudulent stateme
or representations as to any matter within its jurisdiction.	* Con Instruction on Beverse Side	AUG 0 5 1999

\* See Instruction on Reverse Side

FARMING SINIS OFFICE

## San Juan 29-6 Unit #11A SF-080662; Unit D, 1080' FNL & 840' FWL Section 7, T29N, R6W; Rio Arriba County, New Mexico

## Procedure used to perf & stimulate the Lewis Shale interval in the existing Mesaverde formation

## 6/8/99

MIRU Key Energy Rig #40. Killed well. ND WH & NU BOPs. PT – OK. RIH & tagged fill @ 5636'. COOH w/178 jts 2-3/8" tubing. RIH w/4-1/2" CIBP & set @ 4950'. Load hole & PT casing & CIBP to 500 psi 30 minutes. Good test. COOH. GIH & ran GR/CC/CBL from 4944' to liner top. Good cement across Lewis interval. Logged 7" from 3473' to surface with TOC @ 1050'. GIH & perforated Lewis Interval @ 1 spf (.38") holes as follows: (Huerfanito Bentonite not present, equivalent stratigraphic depth @ 4037').

4712' - 4715' (3');	4656' - 4659' (3');	4614' - 4617' (3');	4545' - 4548' (3');
4469' - 4472' (3');	4454' - 4457' (3');	4429' - 4432' (3');	4362' - 4365' (3');
4316' - 4319' (3');	4305' - 4308' (3');	4292' - 4295' (3')'	4070' - 4073' (3') Total 36 Holes

RIH w/4-1/2" FB packer & set @ 3890'. RU BJ to acidize Lewis Shale. Pumped 1000 gal 15% HCL acid & ballsealers. Unset packer & knocked balls off. POOH w/packer. RU to frac. MU 4-1/2" FB packer & set @ 3515'. PT - OK. Pumped 70,132 gal 60 Quality  $N_2$  30# X-link Borate foam w/202,400 # 20/40 Brady sand. Total  $N_2$  - 860,000 scf, total fluid to recover 671 bbls. ATP - 2875, ATR - 45 bpm. ISIP - 576 psi. Flowed back on 1/4" and 1/2" chokes for 42 hours.

RD flowback. Released & COOH. GIH and cleaned out sand & then drilled out CIBP @ 4850'. Chased debris to 5636'. RIH w/2-3/8" tubing and landed @ 5521' with "F" nipple set @ 3488'. ND BOP & NU WH. PT to 1500 psi. OK. Pumped off expendable check and RD & released rig 1600 hrs 6/14/99. Turned over to production department.