FARMINGTON, NEW MEXICO 87401 5525 HWY 64 NBU 3004

September 28, 1995

State of New Mexico
Oil Conservation Division
ATTN: MR. WILLIAM J. LEMAY
310 Old Santa Fe Trail, Room 206
Santa Fe, NM



OIL CON. DIV.

RE: Exception for Unorthodox Location and Field Rules
San Juan 29-5 Unit #88 and #89 Wells

Gentlemen:

The San Juan 29-5 Unit #88 and #89 wells were drilled in 1978 as Basin Dakota producers at unorthodox locations. These wells were drilled by Northwest Pipeline Company as prior operator of the 29-5 Unit.

Phillips Petroleum Company, as current operator of the San Juan 29-5 Unit, wishes to recomplete the #88 and #89 wells to the Blanco Mesaverde. These wells will be recompleted as replacement wells for the existing #34 and #35 Mesaverde wells. Phillips request approval of the unorthodox locations for these Blanco Mesaverde recompletions.

Please note that all offsetting Blanco Mesaverde locations are within the boundaries of the San Juan 29-5 Unit.

Feel free to contact me if additional information is needed.

Very truly yours,

Patrick H. Noah Senior Land Specialist

Pater 14 17 oux

San Juan Basin (505) 599-3410

cc: Ed Hasely

Ernie Busch-OCD, Aztec

pnoah\corr\2958889.ltr\ga