Form 3150-5 (November 1983) (Formerly 9-331)	DEPARTMEN	TED STATES TOF THE INTERIC LAND MANAGEMENT	8UBMIT IN TRIPLICATE® (Other instructions on re-)R verse side)	Budget Bureau Expires August 5. LEASE DESIGNATION SF-079756	No. 1004-0135 31, 1985 AND SERIAL NO.	
		AND REPORTS O		6. IF INDIAN, ALLOTTE	OR TRIBE HAME	
OIL GAB WELL 2	OTRE			7. UNIT AGREEMENT NA	ME	
2. NAME OF OPERATOR				S. FARM OR LEASE NAME		
Amoco Produc		* 		Romero Feder	al	
501 Airport	Drive, Farm	ington, NM 87401	Ate requirementer 1984	1		
4. LOCATION OF WELL (Rep See also space 17 below At surface	.)	x 1070' FWL	R E 191984	10. PIELD AND POOL, OF	-	
	990 LNF	X 1070 FWL	REC 191984	Basin Dakota		
			DEC 1970 MANAGE	2017/201 G		
14. PERMIT NO.	15.	ELEVATIONS (Show whether DF. R.	POR (etc.)	NW/NW Sec. 6		
	i	7550 ' GR		Rio Arriba	NM	
16.	Check Appropr	iate Box To Indicate Nat	ure of Notice, Report, or O	ther Data		
NOTICE OF INTENTION TO:				CENT REPORT OF:		
TEST WATER SHUT-OFF	PCLL OF	A ALTER CASING	WATER SHUT-OFF	repairing w	all	
PRACTURE TREAT		STA.IPKOD BJ	FRACTURE TREATMENT	ALTERING CA	[
REPAIR WELL				ABANDONMENT*		
(Other)	(Note: Report results			of multiple completion on Well etion Report and Log form.)		
subject well tool still casing sund	at 1749'. in the hole y). Gearha	The 5-1/2" casing (the cementing de) became stuck in the was run and cemente tails will be supplicate on the hole.	ed with the log led in the spuc	ging & set	
(Verbal a	approvel u	vas obtained	from John Kell	er on 12-1 DEC 211	VEMX.	
s. I hereby certify that the	foregoing is true and	d correct		OIL CON.	DIV ED FOR RECORD	
SIGNED). Shaw	TITLE Admini	strative Supervisor	DATE		
(This space for Federal v	r State office use)			D	EC 20 15:4	
APPROVED BY COMBITTONS OF APPRO	VAL, IF ANY:	TITLE		BY	GTON, RESUUNCE AREA	
		*See Instructions on Religious			1	