Form 3160-5 UNITED STATES (June 1990) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
	5. Lease Designation and Serial No.	
SUNDRY NOTICES Do not use this form for proposals to Use "APPLICATION I	6. If Indian, Allottee or Tribe Name	
SUB	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Well Well Other	San Juan 29-6 Unit 8. Well Name and No.	
2. Name of Operator Phillips Petroleum Company	SJ 29-6 #210 9. API Well No.	
3. Address and Telephone No.	30-039 <i>-2474</i> 7	
5525 Highway 64, NBU 3004, 4. Location of Well (Footage, Sec., T., R., M., or Surv		10. Field and Pool, or exploratory Area
Unit L, 1990' FSL & 930' FWL Section 20, T29N, R6W		Basin Fruitland Coal 11. County or Parish, State
		Rio Arriba, NM
12. CHECK APPROPRIATE BO	X(s) TO INDICATE NATURE OF NOTICE, REPORT, (OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
X Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other <u>Cavitate & run liner</u>	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Describe Proposed or Completed Operations (Clearly st give subsurface locations and measured and tru	te all pertinent details, and give pertinent dates, including estimated date of starting vertical depths for all markers and zones pertinent to this work.)*	g any proposed work. If well is directionally drille
	cedure used to cavitate the well and run	5-1/2" liner.
	DECE 3 4 1997	ST 10 12 12 12 12 12 12 12 12 12 12 12 12 12

OIL COM, DIV. Regulatory Assistant 3-14-97 Title Conditions of approval, if any: MAR 1 9 1997 Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

San Juan 29-6 #210 SF-078426-A; Unit L, 1990' FSL & 930' FWL Section 20, T29N, R6W, Rio Arriba County, NM

Procedure used to cavitate and run liner.

2/22/97

MIRU Big A #37. NU BOPs. Test-Good. Pulled hanger & COOH w/2-3/8" production tubing. RIH w/DP & DC. Circulate and cleanout to PBTD @ 3170'; COOH. RIH w/9" reamer = under reamed from 2948'-3170'; COOH. Surged well w/air and gas to breakdown coalseam; Circulated and cleaned out to 3170' (TD) with air, water & foamer.

RU 5-1/2" equipment. RIH & set 5-1/2" liner @ 3170' - 5-1/2" X 7" Baker Hyflo III Hanger @ 2892' (53.10' overlap). RU Bluejet and ran GR/CCL. RIH & perf'd w/.75" holes - 4 spf. as follows:

Total		60'	=	240 holes
3040'-3060'	Ξ	20'	=	80 holes
3060'-3080'	=	20'	=	80 holes
3130'-3140'	=	10'	=	40 holes
3160'-3170'	=	10'	=	40 holes

Set FN Packer @ 2878'. Test - OK. Pumped off check. RIH & set BP plug in 1.87 FN @ 2823'. Land hanger & set tubing as follows: 2-7/8" pump out plug set @ 3158' = bottom jt 2-7/8" tubing set @ 3157' = 2-7/8" R-Nipple w/1/78" profile set @ 3126'= 8 jts 2-/78" tubing set @ 3125'= 7" Baker FH packer set @ 2878' = 2-7/8" X 2-3/8" XO Baker L-10 on/off tool w/1/81" FN @ 2869'. 7' spacing in tubing between profile & skirt on on/off tool. Three 2-3/8" X 7" centralizers on bottom 2 jts of 2-3/8" tubing. Skirt for profile set @ 2862' = 6' sub set @ 2861' = bottom jt 2-3/8" tubing set @ 2855' = 2-3/8" FN w/1.87 profile set @ 2823' - 89 jts 2-3/8" tubing w/8' sub under top jt set @ 2822' to surface. RD rig & equipment & release 3/8/97 (2000 hours). Turned well back over to production department.