	G	3.7 ·	Form C-103
Submit 3 Copies To Appropriate District	State of New		Revised March 25, 1999
Office District I	Energy, Minerals and Na	aturar Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 87240 District II	OIL CONCEDUATI	ON DIVISION	30-039-26705
811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NN		STATE X FEE
District IV	Santa PC, 140	101505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			E-289-52
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPORTION OF THE PROPORTI	ES AND REPORTS ON V SALS TO DRILL OR TO DEEP! ATION FOR PERMIT" (FORM	ENJOR PLUGBACK TO A	7. Lease Name or Unit Agreement Name:
PROPOSALS.)	<u> </u>		
1. Type of Well: Oil Well Gas Well X	Other	APR 2000	San Juan 29-6 Unit 009257
2. Name of Operator	Other .		8. Well No.
Phillips Petroleum Company			SJ 29-6 Unit #15B
3. Address of Operator		10 00	9. Pool name or Wildcat
5525 Highway 64, NBU 3004, F	armington, NM 87401		Blanco Mesavede 72319
4. Well Location	· · · · · · · · · · · · · · · · · · ·		
Unit Letter D :	746'feet from the	North line and	261' feet from the West line
Unit Letter:	740 leet nom the	mic and	
Section 2	Township 29N	Range 6W	NMPM County Rio Arriba
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
		6408' GL	Day of an Other Date
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTE		{	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB	
OTHER:		OTHER: D/O CIBP	between LS & MV intervals
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.			
4/3/02 MIRU Key #40. ND WH & NU BOP. PT-OK. Pumped water to kill well. RIH w/mill and C/O fill to CIBP @ 5150'. Drilled out CIBP. Circ. well cleaning to PBTD @ 5849'. COOH. RIH w/2-3/8", 4.7# tubing and set @ 5682' with "F" nipple set @ 5674'. ND BOP, NU WH. Pumped off expendable check. RD & released rig 4/4/02.			
	·		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Fatsy			/Proration Clerk DATE 4/9/02
Time or print name	Patsy Clugston		Telephone No. 505-599-3454
Type or print name	rates oragination		
(This space for State use)  MAY 1 1 2002			
APPROVED BY Conditions of approval, if any:			

APPROVED BY Conditions of approval, if any: