Submit 3 Copies To Appropriate District	State of New					Form C-		
Office	Energy, Minerals and N	Vatura	al Resources			Revised March 25,	1999	
District I 1625 N. French Dr., Hobbs, NM 87240				WELL API NO.				
District II	OIL CONSERVATION DIVISION			30-039-26707				
811 South First, Artesia, NM 87210	1220 South St. Francis Dr.			5. Indicate Type of Lease				
District III 1000 Rio Brazos Rd., Aztec, NM 87410				STATE X FEE				
District IV	·			6. State Oil &	k Gas Le	ease No.		
1220 S. St. Francis Dr., Santa Fe, NM 875	305				-289-3			
SUNDRY NOTICES AND REPORTS ON WELLS MAR 2000 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name:				
1. Type of Well:	ype of Well:				San Juan 29-6 Unit 009257			
2. Name of Operator				8. Well No.				
Phillips Petroleum Company	017654			SJ 29-6 l	Jnit #1	.00		
3. Address of Operator				9. Pool name or Wildcat				
5525 Highway 64, NBU 3004, Farmington, NM 87401				Blanco Mesaverde				
4. Well Location								
Unit Letter	1330'feet from the	Sou	th line and	2250' fe	et from	the East	line	
Section 2	Township 29M		Range 6W	NMPM		County Rio Arri	iba	
	10. Elevation (Show whe		DR, RKB, RT, GR, et 3' GL	(c.)				
11 Charles	Appropriate Box to Ind			Report or 0	Other I	Data		
		icate	CLID	SEQUENT	DED	OPT OF:		
NOTICE OF IN				SEQUENT	NE.F		G [
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK			ALTERING CASING	, L	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILL	ING OPNS.		PLUG AND ABANDONMENT		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB					
OTHER:			OTHER: D/O CIBP	between MV	& Lewi:	s Shale	X	
	Classic state							
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.								
3/22/02 MIRU Key #40. ND WH & NU BOP. PT-OK. GIH w/mill and C/O fill to CIBP @ 5150'. D/O CIBP & chased to PBTD @ 5832'. COOH. RIH w/2-3/8", 4.7# tubing and set 2 5703' with "F" nipple set @ 5696'. ND BOP. NU WH. Pumped off expendable check. RD & released rig 3/25/02. Turned well over to production to put well BOL.								
	1 1 1 1 1 1		lunavuladas and balia	£				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.								
SIGNATURE Falsy	- Cluss -	_ TITI	E Sr. Regulatory	/Proration C	<u>lerk</u> D	ATE3/26/02		
Type or print name	Patsy Clugston			Т	Telephon	ne No. 505-599-34	454	
-7FF-		a	MIT IL DESCRIPTION			MAR 28 20	102	
Oddinal State (1)	STERRING MAYDEN					~ 0 20	UΖ	
APPROVED BYConditions of approval, if any:		_ TIT	LE		DA	ATE		
L								