UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	5.	Lease Number
. Type of Well	6.	SF-078425 If Indian, All. or
GAS		Tribe Name
	7.	Unit Agreement Name
. Name of Operator		
RESOURCES OIL & GAS COMPANY		San Juan 29-7 Unit
OID & GAD COMPANI	8.	
. Address & Phone No. of Operator		San Juan 29-7 U #66
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No. 30-039-07501
. Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
1030'FNL, 970'FEL, Sec.34, T-29-N, R-7-W, NMPM	4.4	Blanco Mesaverde
A	11.	County and State Rio Arriba Co, NM
Type of Submission Type of Action Notice of Intent Abandonment Cf	nange of Pla	
	nange of Pl	and
Recompletion No	ew Construc	tion
X Subsequent Report Plugging Back No	on-Routine	Fracturing
Casing Repair Wa		
Final Abandonment Altering Casing Co	onversion to	o Injection
$ar{}$ Final Abandonment $ar{}$ Altering Casing $ar{}$ Co		o Injection
X_ Other - Tubing repair		o Injection
X_ Other - Tubing repair	ON. SDON. w well & CO	. SD for weekend.
X Other - Tubing repair 3. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. Straper. TOOH. TIH w/5 1/2" RBP. Straper. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" 2 ND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO 2.9# J-55 t	. SD for weekend.
X Other - Tubing repair 3. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. Straper. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" 2 ND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO	. SD for weekend.
X Other - Tubing repair 3. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. Straper. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" 2 ND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO 2.9# J-55 t	. SD for weekend.
X Other - Tubing repair 3. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. Straper. TOOH. TIH w/5 1/2" RBP. Straper. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" 2 ND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO 2.9# J-55 t	. SD for weekend.
X Other - Tubing repair 3. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. S 2-28-97 PT csg to 500 psi, OK. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" 2 ND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO 2.9# J-55 t	. SD for weekend.
X Other - Tubing repair 3. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. Stranger Scraper Scraper Scraper Scraper. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" 2 ND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO 2.9# J-55 t	. SD for weekend.
A Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. Straper and the straper of the strape	ON. SDON. w well & CO 2.9# J-55 t	SD for weekend. og, landed @ 5482'.
A Other - Tubing repair 3. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. Stranger. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" AND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO 2.9# J-55 t	. SD for weekend. bg, landed @ 5482'.
A. Describe Proposed or Completed Operations 2-26-97 MIRU. ND WH. NU BOP. TOOH w/175 jts tbg. SDC 2-27-97 TIH w/csg scraper. TOOH. TIH w/5 1/2" RBP. String 12-28-97 PT csg to 500 psi, OK. TOOH w/RBP. TIH, blow 3-3-97 Blow well & CO. SDON. 3-4-97 Blow well & CO. TOOH. TIH w/168 jts 1 1/2" 2 ND BOP. NU WH. RD. Rig released.	ON. SDON. w well & CO 2.9# J-55 t	SD for weekend. og, landed @ 5482'.
Thereby certify that the foregoing is true and corrections 2. Other - Tubing repair X Other - Tubing repair A Other - Tubing repair X Other - Tubing repair A Describe Proposed or Completed Operations A Other - Tubing repair A Describe Proposed or Completed Operations A Other - Tubing repair A Describe Proposed or Completed Operations A Describe Proposed Operations	ON. SDON. w well & CO 2.9# J-55 t	. SD for weekend. bg, landed @ 5482'.